Mason City Municipal Airport

**Pavement Management Report** 

#### PREPARED BY

Applied Pavement Technology, Inc. 1908 South First Street, Suite 201 Champaign, Illinois 61820 (217) 398-3977 www.appliedpavement.com

#### AUGUST 2025







# MASON CITY MUNICIPAL AIRPORT PAVEMENT MANAGEMENT REPORT

# **Prepared For:**



Iowa Department of Transportation Modal Transportation Bureau 800 Lincoln Way Ames, Iowa 50010 515-239-1101 https://iowadot.gov/modes-travel/aviation

# **Prepared By:**



Applied Pavement Technology, Inc. 1908 South First Street, Suite 201 Champaign, Illinois 61820 217-398-3977 https://www.appliedpavement.com

#### In Association With:



Robinson Engineering Company Consulting Engineers 819 Second Street NE Independence, Iowa 50644 319-334-7211

# **TABLE OF CONTENTS**

INTRODUCTION	
PAVEMENT INVENTORY	3
PAVEMENT EVALUATION	
Pavement Evaluation Procedure	
Pavement Evaluation Results	
Inspection Comments	
Runways	
Taxiways	
Apron	
T-Hangar	
PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM	
Analysis Parameters	
Critical PCIs	
Localized Preventive Maintenance Policies and Unit Costs	
Major Rehabilitation Unit Costs	
Budget and Inflation Rate	
Analysis Approach	
Analysis Results	
General Maintenance Recommendations	
FAA Requirements (Public Law 103-305)	
FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program	
SUMMARY	
REFERENCES	28
LIST OF FIGURES	
Figure 1. Pavement condition versus cost of repair.	
Figure 2. Pavement area by branch use at Mason City Municipal Airport	
Figure 3. Mason City Municipal Airport network definition map	
Figure 4. Visual representation of PCI scale on typical pavement surfaces	
Figure 5. PCI versus repair type	
Figure 6. Pavement area by PCI range at Mason City Municipal Airport	
Figure 7. Area-weighted PCI by branch use at Mason City Municipal Airport	
Figure 8. Mason City Municipal Airport PCI map	10
LIST OF TABLES	
Table 1, 2025 payement evaluation results	11
Table 1. 2025 pavement evaluation results	
Table 2. 5-year M&R program under an unlimited funding analysis scenario	
TAME O FAVEURU INSURCION TROUN	<b>∠</b> I

# **APPENDIXES**

Appendix A. Cause of Distress Tables	A-1
Appendix B. Inspection Photographs	
Appendix C. Inspection Report	
Appendix D. Work History Report	
Appendix E. Localized Preventive Maintenance Policies and Unit Cost Tables	
Appendix F. Year 2025 Localized Preventive Maintenance Details	

Introduction August 2025

#### INTRODUCTION

Applied Pavement Technology, Inc. (APTech), with assistance from Robinson Engineering Company Consulting Engineers (Robinson), updated the Airport Pavement Management System (APMS) for the Iowa Department of Transportation, Modal Transportation Bureau (Iowa DOT). The APMS provides a means to monitor the condition of the pavements within the State of Iowa and to proactively plan for their preservation.

As part of this project, pavement conditions at Mason City Municipal Airport were visually assessed in March 2025 using the Pavement Condition Index (PCI) procedure. During a PCI inspection, the types, severities, and amounts of distress present on the pavement surface are quantified. This information is then used to develop a composite index that represents the overall condition of the pavement in numerical terms, ranging from 0 (*Failed*) to 100 (*Excellent*). The PCI provides an overall measure of condition and an indication of the level of work that will be required to maintain or repair a pavement. The distress information also provides insight into what is causing the pavement to deteriorate, which is the first step in selecting the appropriate repair action to correct the problem.

Programmed into an APMS, PCI data and results are used to determine when preventive maintenance actions (such as crack or joint sealing) are advisable and to identify the most cost-effective time to perform major rehabilitation (such as an overlay or whitetopping). Delaying maintenance and rehabilitation (M&R) until a pavement structure has seriously degraded can cost many times more than if M&R was applied earlier in a pavement's life cycle, as shown in Figure 1. From a safety perspective, pavement distresses, such as cracks and loose debris, may pose risks in terms of the potential for aircraft tire damage and the ability of a pilot to safely control aircraft.




Figure 1. Pavement condition versus cost of repair.

Introduction August 2025

The pavement evaluation results for Mason City Municipal Airport are presented within this report and can be used by Mason City Municipal Airport, the Iowa DOT, and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement M&R actions at the airport. In addition to this report, the web-based interactive pavement data visualization tool IDEA, containing the information collected during this project, was updated and may be accessed from the <u>Iowa DOT's website</u> or directly (<u>Iowa APMS IDEA</u>).

Pavement Inventory August 2025

#### PAVEMENT INVENTORY

The project began with a review of the existing inventory information pertaining to the pavements at Mason City Municipal Airport. The date of original construction, along with the date of any subsequent rehabilitation; the location of completed work; and the type of work undertaken were gathered. The information was used to update the pavement management database and associated maps, as necessary, to account for pavement-related work that had been undertaken since the last time the airport was evaluated in 2021.

The pavement network at Mason City Municipal Airport was then divided into branches, sections, and sample units. A branch is a single entity that serves a distinct function. For example, a runway is considered a branch because it serves a single function (allowing aircraft to take off and land). Taxiways, aprons, and T-hangars are also separate branches.


Each branch was further divided into sections. Traditionally, sections are defined as parts of the branch that share common attributes, such as cross section, date of last construction, traffic level, and performance. Using this approach, if a runway was built in 1968 and then extended in 1984, it would contain two separate sections.


To estimate the overall condition of a pavement section, each section was subdivided into sample units. Portions of these sample units were evaluated during the pavement inspection, and the collected information was extrapolated to predict the overall section condition and quantities of distress.

Approximately 3,252,400 square feet of pavement were evaluated at Mason City Municipal Airport, as illustrated in Figure 2. This figure also shows the area-weighted age in years of the pavements at the time of the inspection. Figure 3 provides a map that details how the pavement network was divided into management units and identifies the sample units that were evaluated during the pavement inspection at Mason City Municipal Airport.

Pavement Inventory August 2025

Figure 2. Pavement area by branch use at Mason City Municipal Airport.





#### **PAVEMENT EVALUATION**

#### **Pavement Evaluation Procedure**

APTech visually inspected the pavements at Mason City Municipal Airport using the PCI procedure described in:

- FAA Advisory Circular 150/5380-6C, <u>Guidelines and Procedures for Maintenance of</u> Airport Pavements.
- FAA Advisory Circular 150/5380-7B, <u>Airport Pavement Management Program (PMP)</u>.
- ASTM D5340, Standard Test Method for Airport Pavement Condition Index Surveys.

During the PCI inspection, a cursory inspection of the entirety of a pavement section was performed. Sample units identified for more detailed inspection were verified, and adjustments to the selected sample units for inspection were made as needed to ensure an accurate assessment of the pavement's condition. Data pertaining to the types, severities, and quantities of observed pavement distresses were then collected within each sample unit. These data were then used to calculate the composite PCI of each pavement section. The PCI provides a numerical indication of overall pavement condition, as illustrated in Figure 4. The PCI ranges from a value of 0, which represents a pavement in a *Failed* condition, to a value of 100, which represents a pavement in *Excellent* condition with no visible signs of deterioration. It is important to note that factors other than overall PCI need to be considered when identifying the appropriate type of repair, including types of distress present and rate of deterioration. Also, since the PCI does not assess the structural integrity or capacity of the pavement structure, further testing may be needed to validate and refine the treatment strategy.

PCI: 100

PCI: 83

Figure 4. Visual representation of PCI scale on typical pavement surfaces.

Note: Photographs shown are not specific to Mason City Municipal Airport.

PCI: 66

Generally, pavements with relatively high PCIs that are not exhibiting significant load-related distress will benefit from preventive maintenance actions, such as crack sealing or joint resealing. As the PCI drops, the pavements may require major rehabilitation, such as an overlay or whitetopping. In some situations where the PCI has dropped low enough, reconstruction may be the only viable alternative due to the substantial damage to the pavement structure. Figure 5 illustrates how the appropriate repair type varies with the PCI of a pavement section and provides the corresponding colors used for the maps and charts in this report for each range of PCIs.

PCI Range

86-100

71-85

Preventive Maintenance

56-70

Major Rehabilitation

26-40

11-25

Reconstruction

Figure 5. PCI versus repair type.

The types of distress identified during the PCI inspection provide insight into the cause of pavement deterioration, which is useful when selecting M&R strategies. Understanding the cause of distress helps in selecting a rehabilitation alternative that corrects the cause and thus eliminates or delays its recurrence. PCI distress types are characterized as:

- Load-related—These distress types are defined as being caused by aircraft or vehicular traffic and may indicate a structural deficiency. Examples of load-related distress include alligator cracking on asphalt-surfaced pavements and corner breaks on portland cement concrete (PCC) pavements.
- Climate/durability-related—These distress types often signify the presence of aged or environmentally susceptible (or both) material and include durability-related issues.
   Examples of climate/durability-related distress include weathering on asphalt-surfaced pavements, which is climate-related, and durability cracking on PCC pavements, which is durability-related.
- Other—Distress types that fall into this category cannot be attributed solely to load or climate/durability. Examples of this type of distress include depressions on asphaltsurfaced pavements and shrinkage cracking on PCC pavements.

Appendix A identifies the distress types considered during a PCI inspection and describes the likely cause of each distress type. It should be noted that a PCI is based on visual signs of pavement deterioration and does not provide a measure of structural capacity.

#### **Pavement Evaluation Results**

The pavements at Mason City Municipal Airport were inspected in March 2025. The 2025 area-weighted condition of Mason City Municipal Airport is 66, with conditions ranging from 31 to 100 (on a scale of 0 [failed] to 100 [excellent]). During the previous pavement inspection in 2021, the area-weighted PCI of the airport was 66.

Figure 6 summarizes the overall condition of the pavements at Mason City Municipal Airport, and Figure 7 presents area-weighted condition (average PCI adjusted to account for the relative size of the pavement sections) by branch use. Figure 8 is a map that displays the condition of the evaluated pavements. Table 1 summarizes the results of the pavement evaluation. Appendix B presents photographs taken during the PCI inspection, and Appendix C contains detailed information on the distress types observed during the visual survey. Appendix D includes detailed work history information that was collected during the record review process.








Figure 7. Area-weighted PCI by branch use at Mason City Municipal Airport.

(Values on chart are area weighted.)





Pavement Evaluation

Table 1. 2025 pavement evaluation results.

Branch	Section	Surface Type	Section Area (sf)	LCD	2025 PCI	% Distress Due to Load	% Distress Due to Climate/ Durability	% Distress Due to Other	Type of Distress
A01MC	10	PCC	70,816	6/2/2008	85	7	73	20	Corner Spalling, Faulting, Joint Seal Damage, LTD Cracking
A01MC	20	PCC	14,332	6/3/1972	82	35	47	18	Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking, Shrinkage Cracking, Small Patch
A01MC	30	PCC	76,000	6/1/2017	87	48	12	40	Corner Spalling, Faulting, Joint Spalling, Joint Seal Damage, Large Patch, LTD Cracking
A01MC	35	AC	73,174	4/5/2021	93	0	100	0	L&T Cracking, Patching, Weathering
A01MC	40	PCC	38,255	6/1/2018	94	41	32	27	Joint Spalling, Joint Seal Damage, LTD Cracking, Small Patch
A01MC	50	AC	11,660	6/3/2006	52	0	100	0	L&T Cracking, Patching, Raveling, Weathering
A01MC	60	AC	14,360	6/2/2009	37	51	46	3	Alligator Cracking, L&T Cracking, Oil Spillage, Raveling, Rutting, Swelling, Weathering
A01MC	70	PCC	3,843	6/1/1999	52	72	14	14	Corner Break, Faulting, Joint Spalling, Joint Seal Damage, LTD Cracking, Shattered Slab
A01MC	80	PCC	22,940	8/3/2024	100	0	0	0	No Distress
A01MC	90	PCC	15,553	8/3/2024	100	0	0	0	No Distress
R12MC	10	AAC	245,643	5/3/2006	61	0	100	0	L&T Cracking, Raveling, Weathering
R12MC	20	AAC	493,057	5/3/2006	61	0	100	0	L&T Cracking, Raveling, Weathering
R12MC	30	AC	18,816	6/3/2005	61	0	100	0	L&T Cracking, Raveling, Weathering
R12MC	40	AC	43,342	6/3/2005	60	0	100	0	L&T Cracking, Patching, Raveling, Weathering
R18MC	10	AAC	248,664	6/4/2005	61	0	100	0	L&T Cracking, Raveling, Weathering
R18MC	20	AAC	497,500	6/4/2005	60	0	100	0	L&T Cracking, Raveling, Weathering
R18MC	30	AAC	26,450	6/2/2005	62	0	100	0	L&T Cracking, Raveling, Weathering

Table 1. 2025 pavement evaluation results (continued).

Branch	Section	Surface Type	Section Area (sf)	LCD	2025 PCI	% Distress Due to Load	% Distress Due to Climate/ Durability	% Distress Due to Other	Type of Distress
R18MC	40	AAC	52,887	6/2/2005	61	0	100	0	L&T Cracking, Raveling, Weathering
R18MC	50	AAC	49,836	6/2/2005	62	0	100	0	L&T Cracking, Raveling, Weathering
R18MC	60	AAC	99,687	6/2/2005	60	0	100	0	L&T Cracking, Raveling, Weathering
TAMC	10	AAC	287,735	6/2/2006	55	0	100	0	L&T Cracking, Patching, Raveling, Weathering
TAMC	20	AAC	16,030	6/2/2005	58	0	100	0	L&T Cracking, Raveling, Weathering
TAMC	30	AC	98,795	4/5/2021	91	0	100	0	L&T Cracking, Weathering
TBMC	10	AAC	32,450	6/2/2006	60	0	100	0	L&T Cracking, Raveling, Weathering
TBMC	15	APC	11,522	6/1/2006	60	0	100	0	L&T Cracking, Raveling, Weathering
TBMC	20	APC	97,151	6/3/2008	62	0	100	0	L&T Cracking, Raveling, Weathering
TBMC	25	APC	19,896	6/2/2005	55	0	100	0	L&T Cracking, Raveling, Weathering
TBMC	30	AAC	47,702	6/3/2008	63	0	100	0	L&T Cracking, Raveling, Weathering
TBMC	35	AAC	8,092	6/1/2006	61	0	100	0	L&T Cracking, Raveling, Weathering
TCMC	10	AAC	271,802	6/3/2008	62	0	100	0	L&T Cracking, Raveling, Weathering
TCMC	20	AAC	17,885	6/2/2005	62	0	100	0	L&T Cracking, Raveling, Weathering
TH01MC	10	AC	31,494	7/4/2024	100	0	0	0	No Distress
TH01MC	20	AC	4,315	1/1/2000	54	39	61	0	Alligator Cracking, L&T Cracking, Weathering
TH01MC	30	PCC	40,756	1/1/1972	31	71	7	22	Corner Break, Corner Spalling, Faulting, Joint Spalling, Joint Seal Damage, Large Patch, LTD Cracking, Popouts, Shattered Slab
TH01MC	35	AC	128,421	9/3/2021	99	0	100	0	L&T Cracking
TH01MC	40	AC	21,501	7/4/2024	100	0	0	0	No Distress

Mason City Municipal Airport Pavement Management Report

#### Table 1. 2025 pavement evaluation results (continued).

#### Table Notes:

- 1. See Figure 3 for the location of the branch and section.
- 2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
- 3. LCD = last construction date.
- 4. Distress due to load includes distress types that are attributed to a structural deficiency in the pavement, such as alligator cracking or rutting on asphalt-surfaced pavements or shattered slabs on PCC pavements.
- 5. Distress due to climate or durability includes distress types that are attributed to either the aging of the pavement and the effects of the environment (such as weathering, raveling, or block cracking on asphalt-surfaced pavements) or to a materials-related problem (such as durability cracking or alkali-silica reaction [ASR] on PCC pavements). If materials-related distresses were recorded during the inspection, further laboratory testing is required to definitively determine the type present.
- 6. Distress due to other refers to distress types that are not attributed to one factor but rather may be caused by a combination of factors.
- 7. Distress types are defined by ASTM D5340. L&T cracking = longitudinal and transverse cracking; LTD cracking = longitudinal, transverse, and diagonal cracking; ASR = alkali-silica reaction.

#### **Inspection Comments**

Mason City Municipal Airport was inspected on March 12-13, 2025. There were 36 pavement sections defined during the inspection.

#### Runways

Runway 12/30 was defined by four sections. Sections 10, 20, 30, and 40 contained low- and medium-severity longitudinal and transverse (L&T) cracking and low-severity raveling and weathering. Section 40 also had medium-severity patching observed. On Runway 12/30, the low-severity L&T cracking was both sealed and unsealed, while the medium-severity L&T cracking was due to either unsatisfactory crack sealant or unsealed crack widths that exceeded 1/4 inch.

Runway 18/36 consisted of six sections that contained low- and medium-severity L&T cracking and low-severity raveling and weathering. Sections 40 and 60 also had high-severity L&T cracking observed where either secondary cracking was wider than 1 foot was noted or where the crack width was greater than 3 inches. Throughout Runway 18/36, the low-severity L&T cracking was both sealed and unsealed, while the medium-severity L&T cracking was recorded where crack sealant was unsatisfactory or unsealed crack widths were greater than 1/4 inch.

#### **Taxiways**

Taxiway A was comprised of three sections that contained low- and medium-severity L&T cracking and low-severity weathering. Section 10 also had high-severity L&T cracking, low- and medium-severity patching, low- and high-severity raveling, and medium-severity weathering. Section 20 additionally had low-severity raveling observed. On Taxiway A, the low-severity L&T cracking was both sealed and unsealed, while the medium-severity L&T cracking was due to either the development of secondary cracking, unsatisfactory crack sealant, or unsealed crack widths that exceeded 1/4 inch. The high-severity L&T cracking was recorded in areas where the crack width was greater than 3 inches.

Taxiway B was defined by six sections that contained low- and medium-severity L&T cracking and low-severity raveling and weathering. Areas of medium- and high-severity weathering were also observed in Section 10 where the surface had been abraded from paint removal, leaving the coarse aggregate exposed. In Section 25, high-severity L&T cracking was observed where either secondary cracking wider than 1 foot had developed or the crack width was greater than 3 inches. A small amount of medium-severity raveling was also recorded in Section 35. Throughout this taxiway, the low-severity L&T cracking was both sealed and unsealed, while the medium-severity L&T cracking was recorded where either crack sealant was unsatisfactory or unsealed crack widths exceeded 1/4 inch.

Taxiway C consisted of two sections. Section 10 contained all severities of L&T cracking and low-severity raveling and weathering. Medium- and high-severity L&T cracking and low-severity raveling and weathering were recorded in Section 20. On this taxiway, the low-severity L&T cracking was unsealed; the medium-severity L&T cracking was due to either unsatisfactory crack sealant or unsealed crack widths greater than 1/4 inch; and the high-severity L&T cracking was recorded where the crack width was greater than 3 inches.

#### **Apron**

The apron area was defined by ten sections. Section 10 contained high-severity joint seal damage and low-severity corner spalling, faulting, and longitudinal, transverse, and diagonal (LTD) cracking. In Section 20, medium-severity corner spalling and small patching, low- and high-severity joint seal damage, low- and medium-severity joint spalling and LTD cracking, and shrinkage cracking were observed. High-severity corner spalling; low-severity faulting, joint seal

damage, and large patching; medium-severity joint spalling; and low- and medium-severity LTD cracking were observed in Section 30. Low-severity L&T cracking and weathering were identified in Section 35. An atypical area of low-severity patching was observed and recorded as an additional sample unit in accordance with ASTM D5340. The low-severity L&T cracking was unsealed. Section 40 contained low-severity joint seal damage and small patching and mediumseverity joint spalling and LTD cracking. Low- and medium-severity L&T cracking and weathering and low-severity patching and raveling were identified in Section 50. The lowseverity L&T cracking was unsealed, while the medium-severity L&T cracking was recorded where either the crack sealant was in an unsatisfactory condition or where unsealed crack widths exceeded 1/4 inch. Section 60 was in Poor condition with low- and medium-severity alligator cracking, rutting, and L&T cracking; oil spillage; medium- and high-severity raveling; low-severity swelling; and medium-severity weathering observed. The low-severity L&T cracking was unsealed, while the medium-severity L&T cracking was recorded where either the crack sealant was unsatisfactory, secondary cracking had developed, or unsealed crack widths were greater than 1/4 inch. Section 70 had medium- and high-severity corner break, low-severity faulting, high-severity joint seal damage and shattered slab, and medium-severity joint spalling and LTD cracking recorded. Sections 80 and 90 were recently constructed and in Excellent condition with no distresses observed at the time of inspection.

## T-Hangar

The T-hangar area contained five sections. Sections 10 and 40 were recently rehabilitated and in *Excellent* condition with no distresses observed. Section 20 contained medium-severity weathering and low- and medium-severity alligator cracking and L&T cracking. The alligator cracking was observed both along the edge of the pavement and in the wheel path. Section 30 was in *Poor* condition with medium- and high-severity corner break, low-severity corner spalling and large patching, low- and medium-severity faulting and LTD cracking, high-severity joint seal damage, medium-severity joint spalling, popouts, and all severities of shattered slab. Low-severity, unsealed L&T cracking was observed in Section 35.

#### PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM

Using the information collected during the pavement inspection, the PAVER pavement management software was used to develop a 5-year M&R program for Mason City Municipal Airport. In addition, a 1-year plan for localized preventive maintenance (such as crack sealing and patching) was prepared.

# **Analysis Parameters**

#### Critical PCIs

PAVER uses critical PCIs to determine whether localized preventive maintenance or major rehabilitation is the appropriate repair action. Above the critical PCI, localized preventive maintenance activities are recommended. Below the critical PCI, major rehabilitation actions, such as an overlay or reconstruction, are recommended. The lowa DOT set the critical PCIs at 65 for runways, 60 for taxiways, and 55 for aprons and T-hangars.

# Localized Preventive Maintenance Policies and Unit Costs

Localized preventive maintenance policies were developed for asphalt-surfaced and PCC pavements. These policies, shown in Appendix E, identify the localized preventive maintenance actions that the lowa DOT considered appropriate to correct the different distress types and severities. The lowa DOT provided unit costs for each of the localized preventive maintenance actions included in these policies, and these costs are detailed in Appendix E. Please note that this information is of a general nature for the entire State. The localized preventive maintenance policies and unit costs may require adjustments to reflect specific conditions at Mason City Municipal Airport.

## Major Rehabilitation Unit Costs

PAVER estimates the cost of major rehabilitation based on the predicted PCI of the pavement section. The lowa DOT provided the costs for major rehabilitation, and they are presented in Appendix E. If major rehabilitation is recommended in the 5-year program, further engineering investigation will be needed to identify the most appropriate rehabilitation action and to estimate the cost of such work more accurately.

#### **Budget and Inflation Rate**

An unlimited budget with a start date of July 1, 2025, and an inflation rate of 2.3 percent was used during the analysis.

#### **Analysis Approach**

The 5-year M&R program was prepared with the goal of maintaining the pavements above established critical PCIs. During this analysis, major rehabilitation was recommended for pavements in the year they dropped below their critical PCI. For the first year (2025) of the analysis only, a localized preventive maintenance plan was developed for those pavement sections that were above their critical PCI. If major rehabilitation was triggered for a section in 2026 or 2027, then localized preventive maintenance was not recommended for 2025. While localized preventive maintenance should be an annual undertaking at Mason City Municipal Airport, it is not possible to accurately predict the propagation of cracking and other distress types. Therefore, the airport should budget for maintenance every year and can use the 2025 localized preventive maintenance plan as a baseline for that work. As the pavements age, it can be assumed that the amount of localized preventive maintenance required will increase.

# **Analysis Results**

A summary of the M&R program for Mason City Municipal Airport is presented in Table 2. Detailed information on the recommended localized preventive maintenance plan for 2025 is provided in Appendix F.

Table 2. 5-year M&R program under an unlimited funding analysis scenario.

			Surface		Estimated
Year	Branch	Section	Type	Type of Repair	Cost
2025	A01MC	10	PCC	Preventive Maintenance	\$29,477
2025	A01MC	20	PCC	Preventive Maintenance	\$3,273
2025	A01MC	30	PCC	Preventive Maintenance	\$1,208
2025	A01MC	40	PCC	Preventive Maintenance	\$889
2025	A01MC	50	AC	Major Rehabilitation	\$62,265
2025	A01MC	60	AC	Major Rehabilitation	\$162,118
2025	A01MC	70	PCC	Major Rehabilitation	\$34,278
2025	R12MC	10	AAC	Major Rehabilitation	\$1,311,750
2025	R12MC	20	AAC	Major Rehabilitation	\$2,632,957
2025	R12MC	30	AC	Major Rehabilitation	\$100,479
2025	R12MC	40	AC	Major Rehabilitation	\$231,449
2025	R18MC	10	AAC	Major Rehabilitation	\$1,327,882
2025	R18MC	20	AAC	Major Rehabilitation	\$2,656,683
2025	R18MC	30	AAC	Major Rehabilitation	\$141,245
2025	R18MC	40	AAC	Major Rehabilitation	\$282,420
2025	R18MC	50	AAC	Major Rehabilitation	\$266,128
2025	R18MC	60	AAC	Major Rehabilitation	\$532,335
2025	TAMC	10	AAC	Major Rehabilitation	\$1,536,524
2025	TAMC	20	AAC	Major Rehabilitation	\$85,601
2025	TAMC	30	AC	Preventive Maintenance	\$350
2025	TBMC	10	AAC	Major Rehabilitation	\$173,285
2025	TBMC	15	APC	Major Rehabilitation	\$61,528
2025	TBMC	25	APC	Major Rehabilitation	\$106,246
2025	TH01MC	20	AC	Major Rehabilitation	\$23,042
2025	TH01MC	30	PCC	Major Rehabilitation	\$768,668
2026	TBMC	20	APC	Major Rehabilitation	\$530,718
2026	ТВМС	35	AAC	Major Rehabilitation	\$44,205
2026	TCMC	10	AAC	Major Rehabilitation	\$1,484,805
2026	TCMC	20	AAC	Major Rehabilitation	\$97,703
2027	TBMC	30	AAC	Major Rehabilitation	\$266,581

Total Estimated Cost: \$14,956,000

Table 2. 5-year M&R program under an unlimited funding analysis scenario (continued).

#### Table Notes:

- 1. See Figure 3 for the location of the branch and section.
- 2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
- 3. Type of Repair: Major Rehabilitation, such as pavement reconstruction or an overlay; Localized Preventive Maintenance, such as crack sealing or patching.
- 4. The estimated costs provided are of a general nature for the entire State and may require adjustments to reflect specific conditions at Mason City Municipal Airport.

The recommendations made in this report are based on a broad network-level analysis and meant to provide Mason City Municipal Airport with an indication of the type of pavement-related work required during the next 5 years. Further engineering investigation may be necessary to identify which repair action is most appropriate. In addition, the cost estimates provided are based on overall unit costs for the entire State, and Mason City Municipal Airport should adjust the plan to reflect local costs.

Because an unlimited budget was used in the analysis, it is possible that the pavement repair program may need to be adjusted to consider economic or operational constraints. The identification of a project need does not necessarily mean that State or Federal funding will be available in the year it is indicated. It is important to remember that regardless of the recommendations presented within this report, Mason City Municipal Airport is responsible for repairing pavements where existing conditions pose a hazard to safe operations.

#### **General Maintenance Recommendations**

In addition to the specific maintenance actions presented in Appendix F, it is recommended that the following strategies be considered for prolonging pavement life:

- 1. Regularly inspect all safety areas of the airport and document all inspection activity. A sample form that can be used to perform these inspections is provided in Table 3 of this report.
- Provide a method of tracking all maintenance activities that occur because of these inspections. This documentation needs to be reported to the FAA and the lowa DOT. This information is used to update the APMS records and is required to remain in compliance with Public Law 103-305 (see the next section of this report for further information on this law).
- 3. Conduct an aggressive campaign against weed growth through timely herbicide applications and mowing programs of the safety areas. Vegetation growth in pavement cracks is destructive and significantly increases the rate of pavement deterioration.
- 4. Implement a periodic crack and joint sealing program. Keeping water and debris out of the pavement system by sealing cracks and joints is a proven and cost-effective method for extending the life of the pavement system.
- 5. Ensure all edges of pavement maintain the required 1.5-inch lip. This enables the water to drain away from the pavement system.
- 6. Closely monitor the movement of heavy equipment (particularly farming, construction, mowing, and fueling equipment) to make sure it is only operating on pavements that are designed to accommodate heavy loads. Failure to restrict heavy equipment to appropriate areas may result in the premature failure of airport pavements.

### FAA Requirements (Public Law 103-305)

Because Mason City Municipal Airport is in the National Plan of Integrated Airport Systems (NPIAS), the airport sponsor is required to keep the airport in a viable operating condition. This includes maintaining airport pavements in accordance with Public Law 103-305. Public Law 103-305 states that after January 1, 1995, NPIAS airport sponsors must provide assurances or certifications that an airport has implemented an effective airport pavement maintenance management system (PMMS) before the airport will be considered for Federal funding of pavement replacement or reconstruction projects. To be in full compliance with the Federal law, the PMMS must include the following components at minimum: pavement inventory, pavement inspections, record keeping, information retrieval, and program funding.

This report serves as a complete pavement inventory and detailed inspection. To remain in compliance with the law, Mason City Municipal Airport will also need to undertake monthly driveby inspections of pavement conditions and track pavement-related maintenance activities.

FAA Advisory Circular 150/5380-7B provides detailed guidance pertaining to the requirements for an acceptable pavement management program. Appendix A of the FAA Advisory Circular 150/5380-7B outlines what needs to be included in a PMP to remain in compliance with this law and Grant Assurance #11. The following is a copy of this appendix, along with instructions for supplementing this report so that all requirements are met. Note that the italicized text is a direct quotation from the FAA Advisory Circular.

#### FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program

**A-1.0.** An effective PMP specifies the procedures to follow to assure that proper preventative and remedial pavement maintenance is performed. The program should identify funding or anticipated funding and other resources available to provide remedial and preventive maintenance activities. An airport sponsor may use any format deemed appropriate, but the program needs to, as a minimum, include the following:

#### A-1.1. Pavement Inventory. The following must be depicted:

a. Identification of all runways, taxiways, and aprons with pavement broken down into sections each having similar properties.

The network definition map provided in Figure 3 of this report shows the location of all runways, taxiways, aprons, and T-hangars at Mason City Municipal Airport. If any new pavements are constructed or any pavement areas are permanently closed, this map must be updated. Project plans should be submitted to the lowa DOT after project completion.

b. Dimensions of pavement sections.

The dimensions of all runways, taxiways, aprons, and T-hangars are stored in the PAVER database. Appendix C provides information on length, width, and area. In addition, the network definition map provided in Figure 3 is drawn to scale. Any changes to pavement dimensions must be recorded.

c. Type of pavement surface.

The type of pavement for each section at Mason City Municipal Airport is listed in Table 1 of this report and is also stored in the PAVER database. Any changes to the pavement type (through an overlay or reconstruction) must be recorded.

- d. Year of construction and/or most recent major rehabilitation.
  - Dates for pavement construction, rehabilitation, or reconstruction must be recorded. The current pavement history for Mason City Municipal Airport is provided in Appendix D of this report.
- e. Whether AIP [Airport Improvement Program] or PFC [Passenger Facility Charge] funds were used to construct, reconstruct, or repair the pavement.
  - Funding sources for all pavement projects should be recorded.
- **A-1.2. PMP Pavement Inspection Schedule.** Airports must perform a detailed inspection of airfield pavements at least once a year for the PMP. If a pavement condition index (PCI) survey is performed, as set forth in ASTM D5340, "Standard Test Method for Airport Pavement Condition Index Surveys," the frequency of the detailed inspection by PCI surveys may be extended to three years. Less comprehensive routine daily, weekly, and monthly maintenance inspections required for operations should be addressed.

This report consists of a detailed inspection that will extend the inspection period to 3 years. It is the airport sponsor's responsibility to perform monthly drive-by inspections. A sample pavement inspection report form is provided in Table 3 of this report.

- **A-1.3. Record Keeping.** The airport must record and keep on file complete information about all detailed inspections and maintenance performed until the pavement system is replaced. The types of distress, their locations, and remedial action, scheduled or performed, must be documented. The minimum information recorded includes:
  - a. Inspection date
  - b. Location
  - c. Distress types
  - d. Maintenance scheduled or performed

Items A through C are satisfied by this inspection report. Item D is the responsibility of the airport, as is record keeping of the monthly drive-by inspections.

**A-1.4.** Information Retrieval. An airport sponsor may use any form of record keeping it deems appropriate so long as the information and records from the pavement survey can generate required reports, as necessary.

Keep this report, monthly drive-by inspection reports, construction updates, and all records of maintenance activities in a readily accessible location so that they can be easily retrieved as requested by the FAA.

Table 3. Pavement inspection report.

Inspected By:	
Data Inapportadi	
Date Inspected:	

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
A01MC	10					
A01MC	20					
A01MC	30					
A01MC	35					
A01MC	40					
A01MC	50					

Table 3. Pavement inspection report (continued).

Inspected By:		
Date Inspected:		

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
A01MC	60					
A01MC	70					
A01MC	80					
A01MC	90					
R12MC	10					
R12MC	20					

Inspected By:	
Date Inspected:	

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
R12MC	30					
R12MC	40					
R18MC	10					
R18MC	20					
R18MC	30					
R18MC	40					

Table 3. Pavement inspection report (continued).

Inspected By:		
Date Inspected:		

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
R18MC	50					
R18MC	60					
TAMC	10					
TAMC	20					
TAMC	30					
ТВМС	10					

Inspected By:		
Date Inspected:		

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
ТВМС	15					
ТВМС	20					
ТВМС	25					
ТВМС	30					
ТВМС	35					
TCMC	10					

Pavement Maintenance and Rehabilitation Program

Table 3. Pavement inspection report (continued)
---

Inspected By:	
Date Inspected:	

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
TCMC	20					
TH01MC	10					
TH01MC	20					
TH01MC	30					
TH01MC	35					
TH01MC	40					

Table Note: See Figure 3 for the location of the branch and section.

Summary August 2025

# **SUMMARY**

This report documents the results of the pavement evaluation conducted at Mason City Municipal Airport. A visual inspection of the pavements in 2025 found that the overall condition of the pavement network is a PCI of 66. A 5-year pavement repair program, shown in Table 2, was generated for Mason City Municipal Airport, which revealed that approximately \$14,956,000 needs to be expended on M&R. Mason City Municipal Airport should utilize these study results to assist in planning for future maintenance needs as part of the airport CIP planning process.

References August 2025

#### **REFERENCES**

ASTM International (ASTM). Standard Test Method for Airport Pavement Condition Index Surveys. D5340. ASTM International, West Conshohocken, PA.

Federal Aviation Administration Authorization Act of 1994. Public Law No. 103-305. Vol 108 Stat. 1569. 1994.

Federal Aviation Administration (FAA). <u>Guidelines and Procedures for Maintenance of Airport Pavements</u>. Advisory Circular 150/5380-6C. Federal Aviation Administration, Washington, DC.

Federal Aviation Administration (FAA). <u>Airport Pavement Management Program (PMP)</u>. Advisory Circular 150/5380-7B. Federal Aviation Administration, Washington, DC.

US Army Corps of Engineers (USACE). 2009. <u>Asphalt Surfaced Airfields</u>. PAVER Distress Identification Manual. USACE, Washington, DC.

US Army Corps of Engineers (USACE). 2009. <u>Concrete Surfaced Airfields</u>. PAVER Distress Identification Manual. USACE, Washington, DC.

US Army Corps of Engineers (USACE). 2021. PAVER. (Software). US Army Corps of Engineers, Transportation Systems Center, Omaha, NE.

# APPENDIX A CAUSE OF DISTRESS TABLES

Cause of Distress Tables August 2025

Table A-1. Cause of pavement distress, asphalt-surfaced pavements (USACE 2009a).

Distress Type	Probable Cause of Distress
Alligator Cracking	Fatigue failure of the asphalt surface under repeated traffic loading.
Bleeding	Excessive amounts of asphalt cement or tars in the mix or low air void content, or both.
Block Cracking	Shrinkage of the asphalt and daily temperature cycling; it is not load associated.
Corrugation	Traffic action combined with an unstable pavement layer.
Depression	Settlement of the foundation soil or can be "built up" during construction.
Jet-Blast Erosion	Bituminous binder has been burned or carbonized.
Joint Reflection Cracking	Movement of the concrete slab beneath the asphalt surface due to thermal and moisture changes.
L&T Cracking	Cracks may be caused by (1) a poorly constructed paving lane joint, (2) shrinkage of the asphalt surface due to low temperatures or hardening of the asphalt, or (3) reflective cracking caused by cracks in an underlying PCC slab.
Oil Spillage	Deterioration or softening of the pavement surface caused by the spilling of oil, fuel, or other solvents.
Patching	N/A
Polished Aggregate	Repeated traffic applications.
Raveling	Asphalt binder may have hardened significantly, causing coarse aggregate pieces to dislodge.
Rutting	Usually caused by consolidation or lateral movement of the materials due to traffic loads.
Shoving	Where PCC pavements adjoin flexible pavements, PCC "growth" may shove the asphalt pavement.
Slippage Cracking	Low-strength surface mix or poor bond between the surface and the next layer of the pavement structure.
Swelling	Usually caused by frost action or by swelling soil.
Weathering	Asphalt binder and/or fine aggregate may wear away as the pavement ages and hardens.

Cause of Distress Tables August 2025

Table A-2. Cause of pavement distress, PCC pavements (USACE 2009b).

Distress Type	Probable Cause of Distress
ASR	Chemical reaction of alkalis in the cement with certain reactive silica minerals. ASR may be accelerated by the use of chemical pavement deicers.
Blowup	Incompressible materials in the joints.
Corner Break	Load repetition combined with loss of support and curling stresses.
Durability Cracking	Concrete's inability to withstand environmental factors, such as freeze-thaw cycles.
Faulting	Upheaval or consolidation.
Joint Seal Damage	Stripping of joint sealant, extrusion of joint sealant, weed growth, hardening of the filler (oxidation), loss of bond to the slab edges, or absence of sealant in the joint.
LTD Cracking	Combination of load repetition, curling stresses, and shrinkage stresses.
Patching (Small and Large)	N/A
Popouts	Freeze-thaw action in combination with expansive aggregates.
Pumping	Poor drainage, poor joint sealant.
Scaling	Over finishing of concrete, deicing salts, improper construction, freeze-thaw cycles, and poor aggregate.
Shattered Slab	Load repetition.
Shrinkage Cracking	Setting and curing of the concrete.
Spalling (Joint and Corner)	Excessive stresses at the joint caused by infiltration of incompressible materials or traffic loads; weak concrete at the joint combined with traffic loads.

## APPENDIX B INSPECTION PHOTOGRAPHS

A01MC-10. Overview.



A01MC-10. Joint Seal Damage (Sample Unit No. 01).



A01MC-20. Overview.



A01MC-20. LTD Cracking (Sample Unit No. 02) (1).



A01MC-20. LTD Cracking (Sample Unit No. 02) (2).




A01MC-20. Small Patching (Sample Unit No. 02).



A01MC-30. Overview.



A01MC-30. LTD Cracking (Sample Unit No. 12).




A01MC-35. Overview.



A01MC-35. L&T Cracking (Sample Unit No. 09).



A01MC-35. Patching (Additional Sample Unit No. 13).



A01MC-35. Weathering (Sample Unit No. 06).



A01MC-40. Overview.



A01MC-40. LTD Cracking (Sample Unit No. 02).



A01MC-50. Overview.



A01MC-50. L&T Cracking (Sample Unit No. 01).



A01MC-50. Patching (Sample Unit No. 01).



A01MC-50. Weathering (Sample Unit No. 01).



A01MC-60. Overview (1).



A01MC-60. Overview (2).



A01MC-60. L&T Cracking (Sample Unit No. 04).



A01MC-60. Oil-Fuel Damage (Sample Unit No. 03) (1).



A01MC-60. Oil-Fuel Damage (Sample Unit No. 03) (2).



A01MC-60. Rutting (Sample Unit No. 04).



A01MC-60. Swelling (Sample Unit No. 04).



A01MC-70. Overview.



A01MC-70. Shattered Slab (Sample Unit No. 02).



A01MC-80. Overview.



A01MC-90. Overview (1).



A01MC-90. Overview (2).



R12MC-10. Overview.



R12MC-10. L&T Cracking (Sample Unit No. 43).



R12MC-10. Raveling (Sample Unit No. 03).



R12MC-10. Weathering (Sample Unit No. 03).



R12MC-20. Overview.



R12MC-20. L&T Cracking (Sample Unit No. 32).



R12MC-20. L&T Cracking (Sample Unit No. 42).



R12MC-20. Raveling (Sample Unit No. 02).



R12MC-20. Weathering (Sample Unit No. 02).



R12MC-30. Overview.



R12MC-30. L&T Cracking (Sample Unit No. 01).



R12MC-40. Overview.



R12MC-40. L&T Cracking (Sample Unit No. 01).



R18MC-10. Overview.



R18MC-10. L&T Cracking (Sample Unit No. 42).



R18MC-20. Overview.



R18MC-20. L&T Cracking (Sample Unit No. 021).



R18MC-20. L&T Cracking (Sample Unit No. 093).



R18MC-30. Overview.



R18MC-30. L&T Cracking (Sample Unit No. 05).



R18MC-40. Overview.



R18MC-40. L&T Cracking (Sample Unit No. 08).



R18MC-40. L&T Cracking (Sample Unit No. 10) (1).



R18MC-40. L&T Cracking (Sample Unit No. 10) (2).



R18MC-50. Overview.



R18MC-50. L&T Cracking (Sample Unit No. 07).



R18MC-60. Overview.




R18MC-60. L&T Cracking (Sample Unit No. 06).



R18MC-60. L&T Cracking (Sample Unit No. 18).



TAMC-10. Overview.



TAMC-10. L&T Cracking (Sample Unit No. 40).



TAMC-10. L&T Cracking (Sample Unit No. 48).



TAMC-10. Patching (Sample Unit No. 10).



TAMC-10. Weathering (Sample Unit No. 10).



TAMC-20. Overview.



TAMC-20. L&T Cracking (Sample Unit No. 01) (1).




TAMC-20. L&T Cracking (Sample Unit No. 01) (2).



TAMC-20. Raveling (Sample Unit No. 01).



TAMC-30. Overview.



TAMC-30. L&T Cracking (Sample Unit No. 04).



TAMC-30. Weathering (Sample Unit No. 18).



TBMC-10. Overview.



TBMC-10. L&T Cracking (Sample Unit No. 02).



TBMC-10. Weathering (Sample Unit No. 02).



TBMC-15. Overview.



TBMC-15. L&T Cracking (Sample Unit No. 01).



TBMC-20. Overview.



TBMC-20. L&T Cracking (Sample Unit No. 15).



TBMC-25. Overview.



TBMC-25. L&T Cracking (Sample Unit No. 02).



TBMC-25. Raveling (Sample Unit No. 01).



TBMC-30. Overview.



TBMC-30. L&T Cracking (Sample Unit No. 04).



TBMC-30. Raveling (Sample Unit No. 04).




TBMC-35. Overview.



TBMC-35. L&T Cracking (Sample Unit No. 01).



TCMC-10. Overview.



TCMC-10. L&T Cracking (Sample Unit No. 14).



TCMC-10. L&T Cracking (Sample Unit No. 24).




TCMC-10. L&T Cracking (Sample Unit No. 39).



TCMC-20. Overview.



TCMC-20. L&T Cracking (Sample Unit No. 01) (1).



TCMC-20. L&T Cracking (Sample Unit No. 01) (2).



TH01MC-10. Overview.



TH01MC-20. Overview.



TH01MC-20. Alligator Cracking (Sample Unit No. 01).



TH01MC-20. L&T Cracking (Sample Unit No. 01).



TH01MC-30. Overview (1).



TH01MC-30. Overview (2).



TH01MC-30. Popouts (Sample Unit No. 18).



TH01MC-30. Shattered Slab (Sample Unit No. 18) (1).



TH01MC-30. Shattered Slab (Sample Unit No. 18) (2).



TH01MC-35. Overview.



TH01MC-35. L&T Cracking (Sample Unit No. 02).



TH01MC-40. Overview (1).



TH01MC-40. Overview (2).



# APPENDIX C INSPECTION REPORT

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 1

Branch - Section ID: A01MC - 010

Branch Name: APRON 01 Use: APRON

PCI Family: IowaPCCAP NE CommGeneral

Inspection Comments:

Sample Comments:

LCD: 6/2/2008 Surface Type: PCC

Rank: P

Section Area (sf): 70,816.00

Length (ft): 236.00 Width (ft): 300.00

From: . To: .

Slabs: 322 Section Comments:

Slab Length (ft): 15.40 Slab Width (ft): 14.30 Joint Length (ft): 9,014.49

Last Insp Date: 3/12/2025

PCI: 85

Total Samples: 16 Surveyed: 6

Sample Number: 01

Sample Type: R Sample Comments:

Sample PCI: 84

Sample Area (Slabs): 20.00

 65 JT SEAL DMG
 H
 20.00 Slabs

 75 CORNER SPALL
 L
 2.00 Slabs

Sample Number: 05

Sample Type: R

Sample PCI: 88

Sample Area (Slabs): 20.00

65 JT SEAL DMG H 20.00 Slabs

Sample Number: 06

Sample Type: R Sample Comments:

Sample PCI: 81

Sample Area (Slabs): 20.00

65 JT SEAL DMG H 20.00 Slabs 71 FAULTING L 3.00 Slabs

Sample Number: 10

Sample Type: R Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 20.00

65 JT SEAL DMG H 20.00 Slabs

Sample Number: 13

Sample Type: R Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 14.00

65 JT SEAL DMG H 14.00 Slabs

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 2

Sample Number: 15

Sample Type: R Sample Comments:

Sample PCI: 84

Sample Area (Slabs): 22.00

 63 LINEAR CR
 L
 1.00 Slabs

 65 JT SEAL DMG
 H
 22.00 Slabs

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW

Branch - S	ection ID: A01MC - 020
------------	------------------------

Branch Name: APRON 01 Use: APRON

Surface Type: PCC

LCD: 6/3/1972

Rank: P

Section Area (sf): 14,332.00

Length (ft): 160.00 Width (ft): 90.00

From: . To: .

Slabs: 105 Section Comments:

Slab Length (ft): 11.90 Slab Width (ft): 11.50 Joint Length (ft): 2,201.81

Last Insp Date: 3/13/2025

PCI: 82 Total Samples: 4 Surveyed: 3 Inspection Comments:

Sample Comments:

PCI Family: IowaPCCAP NE CommGeneral

Sample Number: 01

Sample Type: R

Sample PCI: 92

Sample Area (Slabs): 24.00

65 JT SEAL DMG L 24.00 Slabs 74 JOINT SPALL M 2.00 Slabs

Sample Number: 02

Sample Type: R Sample Comments:

Sample PCI: 73

Sample Area (Slabs): 28.00

63 LINEAR CR L 5.00 Slabs 63 LINEAR CR Μ 1.00 Slabs 65 JT SEAL DMG L 28.00 Slabs 66 SMALL PATCH Μ 1.00 Slabs 74 JOINT SPALL L 2.00 Slabs 75 CORNER SPALL Μ 1.00 Slabs

Sample Number: 03

Sample Type: R Sample Comments:

Sample PCI: 83

Sample Area (Slabs): 24.00

 63 LINEAR CR
 L
 1.00 Slabs

 65 JT SEAL DMG
 H
 24.00 Slabs

 73 SHRINKAGE CR
 N
 1.00 Slabs

Pavement Database: IA 2024 Generate Date: 8/11/2025

1 avenient Database. I/ \ 2027			Ochorate Date. 0/11/2020
Network ID: MCW			Page 4
	Branch - Secti	on ID: A01MC - 030	
Branch Name: APRON 01			Use: APRO
LCD: 6/1/2017 Surface Type: PCC Rank: P Section Area (sf): 76,000.00 Length (ft): 608.00 Width (ft): 125.00 From: . To: .		PCI Family: lowaPCCAP_NE_CommGene	ral
Slabs: 337 Slab Length (ft): 20.30 Slab Width (ft): 11.10 Joint Length (ft): 9,857.69		Section Comments:	
Last Insp Date: 3/12/2025 PCI: 87 Total Samples: 17 Surveyed: 6		Inspection Comments:	
Sample Number: 06			
Sample Type: R Sample PCI: 91 Sample Area (Slabs): 24.00 63 LINEAR CR	L	Sample Comments:  2.00 Slabs	
65 JT SEAL DMG	L	24.00 Slabs	
Sample Number: 10			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 24.00 65 JT SEAL DMG	L	Sample Comments:  24.00 Slabs	
Sample Number: 11	L	24.00 Slabs	
Sample Type: R Sample PCI: 95 Sample Area (Slabs): 24.00 65 JT SEAL DMG 67 LARGE PATCH	L L	Sample Comments:  24.00 Slabs 1.00 Slabs	
Sample Number: 12	<b>_</b>	1.00 51455	
Sample Type: R Sample PCI: 78 Sample Area (Slabs): 27.00		Sample Comments:	
63 LINEAR CR 65 JT SEAL DMG 67 LARGE PATCH 74 JOINT SPALL 75 CORNER SPALL	M L L M H	1.00 Slabs 27.00 Slabs 3.00 Slabs 1.00 Slabs 1.00 Slabs	
Sample Number: 13			
Sample Type: R Sample PCI: 77		Sample Comments:	

63 LINEAR CR L 2.00 Slabs 2.00 Slabs 63 LINEAR CR 65 JT SEAL DMG 24.00 Slabs

Sample Area (Slabs): 24.00

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 5

Sample Number: 14

Sample Type: R Sample Comments:

Sample PCI: 85

Sample Area (Slabs): 24.00

65 JT SEAL DMG L 24.00 Slabs 71 FAULTING L 4.00 Slabs

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 6

PCI Family: IowaACAP NE&NCE

Sample Comments:

Sample Comments:

Branch - Section ID: A01MC - 035

Branch Name: APRON 01 Use: APRON

LCD: 4/5/2021

Surface Type: AC

Rank: P

Section Area (sf): 73,174.00 Length (ft): 1,464.00 Width (ft): 50.00 From: A01MC-30

To: TA-30

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

Last Insp Date: 3/12/2025

PCI: 93

Total Samples: 13 Surveyed: 6

Inspection Comments:

Sample Number: 03

Sample Type: R Sample PCI: 94

Sample Area (SF): 5,000.00

57 WEATHERING L 5.000.00 SF

Sample Number: 06

Sample Type: R

Sample PCI: 94

Sample Area (SF): 5,000.00

> 57 WEATHERING L 5,000.00 SF

Sample Number: 08

Sample Type: R Sample Comments:

Sample PCI: 94

Sample Area (SF): 5,000.00

> 57 WEATHERING L 5,000.00 SF

Sample Number: 09

Sample Type: R Sample Comments:

Sample PCI: 90

Sample Area (SF): 7,000.00

> 48 L & T CR L 21.00 FT lu

57 WEATHERING L 7,000.00 SF

Sample Number: 12

Sample Type: R Sample Comments:

Sample PCI: 94

Sample Area (SF): 5,000.00

> 57 WEATHERING L 5,000.00 SF

Sample Number: 13

Sample Type: A Sample Comments:

Sample PCI: 89

6,325.00 Sample Area (SF):

> 50 PATCHING 100.00 SF 57 WEATHERING 6.225.00 SF ı

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW

Branch - Section ID: A01MC - 040

Branch Name: APRON 01 Use: APRON

LCD: 6/1/2018 Surface Type: PCC

Rank: P

Section Area (sf): 38,255.00

Length (ft): 250.00 Width (ft): 152.00

From: . To: .

Slabs: 170 Section Comments:

Slab Length (ft): 15.00 Slab Width (ft): 15.00 Joint Length (ft): 4,695.97

Last Insp Date: 3/12/2025

PCI: 94 Total Samples: 9 Surveyed: 5 Inspection Comments:

Sample Comments:

Sample Comments:

Sample Comments:

Sample Comments:

PCI Family: IowaPCCAP NE CommGeneral

Sample Number: 01

Sample Type: R Sample PCI: 98

Sample PCI. 90

Sample Area (Slabs): 25.00

65 JT SEAL DMG L 25.00 Slabs

Sample Number: 02

Sample Type: R

Sample PCI: 89

Sample Area (Slabs): 25.00

 63 LINEAR CR
 M
 1.00 Slabs

 65 JT SEAL DMG
 L
 25.00 Slabs

Sample Number: 03

Sample Type: R

Sample PCI: 91

Sample Area (Slabs): 20.00

65 JT SEAL DMG L 20.00 Slabs 74 JOINT SPALL M 2.00 Slabs

Sample Number: 05

Sample Type: R

Sample PCI: 98

Sample Area (Slabs): 15.00

65 JT SEAL DMG L 15.00 Slabs

Sample Number: 08

Sample Type: R Sample Comments:

Sample PCI: 97

Sample Area (Slabs): 25.00

65 JT SEAL DMG L 25.00 Slabs 66 SMALL PATCH L 1.00 Slabs

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 8

Branch -	Section	ID:	ANIMC .	. 050
Dianti -	Section	IV.	AUTIMO :	- 030

Branch Name: APRON 01 Use: APRON

LCD: 6/3/2006 Surface Type: AC

Rank: P

Section Area (sf): 11,660.00

Length (ft): 460.00 Width (ft): 25.00

From: . To: .

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

Last Insp Date: 3/12/2025

PCI: 52 Total Samples: 2 Surveyed: 2

Inspection Comments:

lu

fs w

PR

PCI Family: IowaACAP NE&NCE

#### Sample Number: 01

Sample Type: R Sample Comments:

Sample PCI: 52

Sample Area (SF): 5,875.00

> 48 L & T CR 26.00 FT L 48 L & T CR Μ 180.00 FT **50 PATCHING** L 2,750.00 SF **50 PATCHING** L 2.00 SF 52 RAVELING L 3,123.00 SF **57 WEATHERING** L 3,083.00 SF 57 WEATHERING Μ 40.00 SF

#### Sample Number: 02

Sample Type: R Sample Comments:

Sample PCI: 52

Sample Area (SF): 5,785.00

> 48 L & T CR L 50.00 FT lu 48 L & T CR Μ 406.00 FT fs 385.00 SF **50 PATCHING** L 52 RAVELING L 5,400.00 SF **57 WEATHERING** L 5,400.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW

			Page 9
Branch - Section ID:	A01MC - 060		
			Use: APRON
PCI Fan	nily: IowaACAP_NE&NCE		
Section	Comments:		
Inspecti	on Comments:		
Sample	Comments:		
L L M H M L	70.00 SF 175.00 FT 78.00 FT 20.00 SF 100.00 SF 120.00 SF 3,780.00 SF	lu w	
M M N	50.00 SF 315.00 FT 20.00 SF	W	
M	24.00 SF		
M	3,500.00 SF		
Sample	Comments:		
L L M H M L	40.00 SF 143.00 FT 70.00 FT 20.00 SF 40.00 SF 60.00 SF 20.00 SF	lu w 2ndy	
	Section Inspection  Sample  L L M H M L M Sample  M Sample  L L M M N Sample	Section Comments:   Inspection Comments:     Inspection Comments:     Inspection Comments:     Inspection Comments:     Inspection Comments:     Inspection Comments:   Inspection Co	Section Comments:     Sample Comments:     Sample Comments:   Sample

L

50.00 SF

2,980.00 SF

56 SWELLING

**57 WEATHERING** 

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 10

Branch - Section ID: A01MC - 070

Branch Name: APRON 01 Use: APRON

LCD: 6/1/1999 Surface Type: PCC

Rank: P

Section Area (sf): 3,843.00 Length (ft): 130.00 Width (ft): 30.00

From: . To: .

Slabs: 36

Slab Length (ft): 10.80 Slab Width (ft): 10.00 Joint Length (ft): 593.38

Last Insp Date: 3/12/2025

PCI: 52 Total Samples: 2 Surveyed: 2

PCI Family: IowaPCCAP NE CommGeneral

Section Comments:

Inspection Comments:

Sample Comments:

Sample Comments:

Sample Number: 01

Sample Type: R

Sample PCI: 70

Sample Area (Slabs): 21.00

62 CORNER BREAK 3.00 Slabs Μ Н 21.00 Slabs 65 JT SEAL DMG 71 FAULTING L 2.00 Slabs

Sample Number: 02

Sample Type: R

Sample PCI: 26

Sample Area (Slabs): 15.00

**62 CORNER BREAK** Н 2.00 Slabs **62 CORNER BREAK** Μ 1.00 Slabs 63 LINEAR CR Μ 1.00 Slabs 15.00 Slabs 65 JT SEAL DMG Н 71 FAULTING 1.00 Slabs L 1.00 Slabs 72 SHAT. SLAB Н 74 JOINT SPALL 2.00 Slabs Μ

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 11

Branch - Section ID: A01MC - 080

Branch Name: APRON 01 Use: APRON

LCD: 8/3/2024 Surface Type: PCC

Rank: P

Section Area (sf): 22,940.00

Length (ft): 229.00 Width (ft): 100.00 From: SEE MAP To: SEE MAP

Slabs: 199 Section Comments:

Slab Length (ft): 10.50 Slab Width (ft): 11.00 Joint Length (ft): 3,940.64

Last Insp Date: 3/12/2025 Inspection Comments:

PCI: 100 Total Samples: 6 Surveyed: 4

Sample Number: 01

Sample Type: R Sample PCI: 100

Sample Area (Slabs): 24.00

**NO DISTRESS** 

Sample Number: 02

Sample Type: R

Sample PCI: 100

Sample Area (Slabs): 21.00

**NO DISTRESS** 

Sample Number: 03

Sample Type: R Sample PCI: 100

Sample Area (Slabs): 24.00

**NO DISTRESS** 

Sample Number: 05

Sample Type: R Sample PCI: 100

Sample Area (Slabs): 24.00

**NO DISTRESS** 

PCI Family: IowaPCCAP NE CommGeneral

Sample Comments:

Sample Comments:

Sample Comments:

Sample Comments:

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 12

Branch - Section ID: A01MC - 090

Branch Name: APRON 01 Use: APRON

LCD: 8/3/2024 Surface Type: PCC

Rank: P

Section Area (sf): 15,553.00

Length (ft): 676.00 Width (ft): 23.00 From: SEE MAP To: SEE MAP

Slabs: 135 Section Comments:

Slab Length (ft): 10.50 Slab Width (ft): 11.00 Joint Length (ft): 2,195.92

Last Insp Date: 3/13/2025 Inspection Comments:

PCI: 100 Total Samples: 4 Surveyed: 3

Sample Number: 02

Sample Type: R Sample PCI: 100

Sample Area (Slabs): 20.00

**NO DISTRESS** 

Sample Number: 03

Sample Type: R

Sample PCI: 100

Sample Area (Slabs): 20.00

**NO DISTRESS** 

Sample Number: 04

Sample Type: R Sample PCI: 100

Sample Area (Slabs): 18.00

**NO DISTRESS** 

PCI Family: IowaPCCAP NE CommGeneral

Sample Comments:

Sample Comments:

Sample Comments:

Pavement Database: IA 2024 Generate Date: 8/11/2025

Faverneni Dalabase. IA 2024			Generale Date. 6/11/2023
Network ID: MCW			Page 13
	Branch - Section	n ID: R12MC - 010	
Branch Name: RUNWAY 12/30			Use: RUNWAY
LCD: 5/3/2006 Surface Type: AAC Rank: S Section Area (sf): 245,643.00 Length (ft): 4,938.00 Width (ft): 50.00 From: SEE MAP To: SEE MAP	P	CI Family: lowaAACRW_NE&N0	CE
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	S	ection Comments:	
Last Insp Date: 3/12/2025 PCI: 61 Total Samples: 49 Surveyed: 7	In	spection Comments:	
Sample Number: 03			
Sample Type: R Sample PCI: 62 Sample Area (SF): 5,000.00	S	ample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	23.00 FT 230.00 FT 5,000.00 SF 5,000.00 SF	lu fs w
Sample Number: 08			
Sample Type: R Sample PCI: 63 Sample Area (SF): 5,000.00  48 L & T CR 48 L & T CR	L M	5.00 FT	ls fs w
52 RAVELING 57 WEATHERING	L L	5,000.00 SF 5,000.00 SF	
Sample Number: 13		,	
Sample Type: R Sample PCI: 62 Sample Area (SF): 5,000.00	S	ample Comments:	
48 L & T CR 48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L L M L L	27.00 FT 17.00 FT 212.00 FT 5,000.00 SF 5,000.00 SF	ls Iu fs w
Sample Number: 23			
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,000.00	S	ample Comments:	
48 L & T CR	L	26.00 FT	lu Io

L

Μ

10.00 FT

160.00 FT

5,000.00 SF

5,000.00 SF

ls

w fs

48 L & T CR

48 L & T CR

52 RAVELING

**57 WEATHERING** 

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW

Network ID: MCW				Page 14
Sample Number: 28				
Sample Type: R	Sampl	e Comments:		
Sample PCI: 60				
Sample Area (SF): 5,000.00				
48 L & T CR	L	60.00 FT	lu	
48 L & T CR	M	233.00 FT	fs w	
52 RAVELING	L	5,000.00 SF		
57 WEATHERING	L	5,000.00 SF		
Sample Number: 33				
Sample Type: R	Sampl	e Comments:		
Sample PCI: 59				
Sample Area (SF): 5,000.00				
48 L & T CR	L	42.00 FT	ls	
48 L & T CR	L	31.00 FT	lu	
48 L & T CR	M	266.00 FT	fs w	
52 RAVELING	L	5,000.00 SF		
57 WEATHERING	L	5,000.00 SF		
Sample Number: 43				
Sample Type: R	Sampl	e Comments:		

Sample Type: R	Sample Comments:
----------------	------------------

Sample PCI: 59

Sample Area (SF): 5,000.00

48 L & T CR	L	29.00 FT	lu
48 L & T CR	L	13.00 FT	ls
48 L & T CR	M	300.00 FT	fs w
52 RAVELING	L	5,000.00 SF	
57 WEATHERING	L	5.000.00 SF	

Pavement Database: IA 2024 Generate Date: 8/11/2025

			_	
Network ID: MCW				Page 15
	Branch - Section	on ID: R12MC - 020		
Branch Name: RUNWAY 12/30				Use: RUNWA
LCD: 5/3/2006 Surface Type: AAC Rank: S Section Area (sf): 493,057.00 Length (ft): 4,938.00 Width (ft): 100.00 From: SEE MAP To: SEE MAP		PCI Family: IowaAACRW_NE&N	CE	
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):		Section Comments:		
Last Insp Date: 3/12/2025 PCI: 61 Total Samples: 98 Surveyed: 10		Inspection Comments:		
Sample Number: 02				
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000.00		Sample Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	14.00 FT 260.00 FT 5,000.00 SF 5,000.00 SF	lu fs w	
Sample Number: 12				
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000.00		Sample Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	26.00 FT 260.00 FT 5,000.00 SF 5,000.00 SF	ls fs w	
Sample Number: 22				
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000.00		Sample Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	15.00 FT 275.00 FT 5,000.00 SF 5,000.00 SF	lu fs w	
Sample Number: 32				
Sample Type: R Sample PCI: 57 Sample Area (SF): 5 000 00		Sample Comments:		

Sample Area (SF): 5,000.00

48 L & T CR 10.00 FT ls 48 L & T CR L 6.00 FT lu 48 L & T CR 390.00 FT fs w **52 RAVELING** L 5,000.00 SF 57 WEATHERING 5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 16

Network ID: MCW					Page 16
Sample Number: 42					
Sample Type: R Sample PCI: 60 Sample Area (SF):	5,000.00	Sample	Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERII	NG	L L M L L	18.00 FT 11.00 FT 270.00 FT 5,000.00 SF 5,000.00 SF	lu Is fs w	
Sample Number: 53					
Sample Type: R Sample PCI: 63 Sample Area (SF):	5,000.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERII	NG	L M L L	14.00 FT 210.00 FT 5,000.00 SF 5,000.00 SF	lu fs w	
Sample Number: 63					
Sample Type: R Sample PCI: 64 Sample Area (SF):	5,000.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERII	NG	L M L L	28.00 FT 160.00 FT 5,000.00 SF 5,000.00 SF	lu fs w	
Sample Number: 73					
Sample Type: R Sample PCI: 61 Sample Area (SF):	5,000.00	Sample	Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERII	NG	L L M L L	10.00 FT 12.00 FT 260.00 FT 5,000.00 SF 5,000.00 SF	ls lu fs w	
Sample Number: 83					
Sample Type: R Sample PCI: 62 Sample Area (SF):	5,000.00	Sample	Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERII	NG	L L M L L	12.00 FT 24.00 FT 210.00 FT 5,000.00 SF 5,000.00 SF	lu fs w	

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 17

5,000.00 SF

Sample Number: 93

Sample Type: R Sample Comments:

Sample PCI: 63

Sample Area (SF): 5,000.00

**57 WEATHERING** 

 48 L & T CR
 L
 11.00 FT
 Is

 48 L & T CR
 L
 9.00 FT
 Iu

 48 L & T CR
 M
 213.00 FT
 fs w

 52 RAVELING
 L
 5,000.00 SF

L

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 18

Network ID: MCVV				Page 18
	Branch - Section ID:	R12MC - 030		
Branch Name: RUNWAY 12/30				Use: RUNWAY
LCD: 6/3/2005 Surface Type: AC Rank: S Section Area (sf): 18,816.00 Length (ft): 380.00 Width (ft): 50.00 From: SEE MAP To: SEE MAP	PCI Fai	mily: lowaACRW_NE		
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	Comments:		
Last Insp Date: 3/12/2025 PCI: 61 Total Samples: 4 Surveyed: 3	Inspect	ion Comments:		
Sample Number: 01				
Sample Type: R Sample PCI: 57 Sample Area (SF): 5,000.00	Sample	Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M M L L	39.00 FT 50.00 FT 300.00 FT 5,000.00 SF 5,000.00 SF	lu at break fs fs w	
Sample Number: 02		,		
Sample Type: R Sample PCI: 63	Sample	Comments:		
Sample Area (SF): 5,000.00  48 L & T CR  48 L & T CR  52 RAVELING  57 WEATHERING	L M L L	29.00 FT 202.00 FT 5,000.00 SF 5,000.00 SF	lu fs w	
Sample Number: 04				
Sample Type: R Sample PCI: 64 Sample Area (SF): 6,068.00	Sample	Comments:		

M

L

48 L & T CR

52 RAVELING

**57 WEATHERING** 

201.00 FT

6,068.00 SF

6,068.00 SF

fs w

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 19

Network ID: MCW				Page 19
	Branch - Section ID	: R12MC - 040		
Branch Name: RUNWAY 12/30				Use: RUNWAY
LCD: 6/3/2005 Surface Type: AC Rank: S Section Area (sf): 43,342.00 Length (ft): 380.00 Width (ft): 100.00 From: SEE MAP To: SEE MAP	PCI Fa	amily: IowaACRW_NE		
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Sectio	n Comments:		
Last Insp Date: 3/12/2025 PCI: 60 Total Samples: 9 Surveyed: 4	Inspec	ction Comments:		
Sample Number: 01				
Sample Type: R Sample PCI: 55 Sample Area (SF): 5,000.00	Sampl	e Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING	L M M M L	43.00 FT 243.00 FT 50.00 FT 12.00 SF 4,978.00 SF 4,978.00 SF	lu fs w at break fs	
Sample Number: 05				
Sample Type: R Sample PCI: 64 Sample Area (SF): 4,525.00	Sampl	e Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	35.00 FT 150.00 FT 4,525.00 SF 4,525.00 SF	lu fs w	
Sample Number: 06				
Sample Type: R Sample PCI: 58 Sample Area (SF): 5,000.00	Sampl	le Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 50 PATCHING 52 RAVELING	L M M M L	26.00 FT 187.00 FT 50.00 FT 24.00 SF 4,976.00 SF	lu fs w at break fs	
EZ MENTUEDINO	ı	4.070.00.CF		

4,976.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 20

Sample Number: 09

Sample Type: R Sample Comments:

Sample PCI: 64

Sample Area (SF): 5,000.00

 48 L & T CR
 L
 39.00 FT
 lu

 48 L & T CR
 M
 50.00 FT
 fs w

 52 RAVELING
 L
 5,000.00 SF

52 RAVELING L 5,000.00 SF 57 WEATHERING L 5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW			Page 2 <sup>-</sup>
	Branch - Section ID:	R18MC - 010	
Branch Name: RUNWAY 18/36			Use: RUNWAY
LCD: 6/4/2005 Surface Type: AAC Rank: P Section Area (sf): 248,664.00 Length (ft): 4,975.00 Width (ft): 50.00 From: SEE MAP To: SEE MAP	PCI Far	mily: lowaAACRW_NE&NC	E
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	Comments:	
Last Insp Date: 3/12/2025 PCI: 61 Total Samples: 50 Surveyed: 7	Inspecti	on Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 60 Sample Area (SF): 5,000.00	Sample	Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	58.00 FT 235.00 FT 5,000.00 SF 5,000.00 SF	lu fs w
Sample Number: 12			
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000.00	Sample	Comments:	
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L L M L L	40.00 FT 25.00 FT 210.00 FT 5,000.00 SF 5,000.00 SF	Is Iu fs
Sample Number: 17			
Sample Type: R Sample PCI: 60 Sample Area (SF): 5,000.00	Sample	Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	66.00 FT 250.00 FT 5,000.00 SF 5,000.00 SF	lu fs
Sample Number: 22			
Sample Type: R Sample PCI: 62 Sample Area (SF): 5,000.00	Sample	Comments:	
48 L & T CR 48 L & T CR	L M	35.00 FT 215.00 FT	lu fs w

L

5,000.00 SF

5,000.00 SF

52 RAVELING

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 22

L

L

Μ

Sample	Number:	32
--------	---------	----

Sample Type: R

Sample PCI: 62

Sample Area (SF):

5,000.00

48 L & T CR 52 RAVELING

57 WEATHERING

Sample Comments:

250.00 FT Μ

L 5,000.00 SF L 5,000.00 SF

Sample Number: 37

Sample Type: R

Sample PCI: 62 5,000.00

Sample Area (SF): 48 L & T CR

48 L & T CR 52 RAVELING

57 WEATHERING

Sample Comments:

L 13.00 FT Μ 250.00 FT L 5,000.00 SF

5,000.00 SF

Sample Number: 42

Sample Type: R

Sample PCI: 62

Sample Area (SF): 5,000.00

48 L & T CR

48 L & T CR

52 RAVELING **57 WEATHERING**  Sample Comments:

12.00 FT

250.00 FT

fs w 2ndy

fs w

lu

fs w

L 5,000.00 SF L 5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 23

Network ID: MCW			Page 23
	Branch - Sect	ion ID: R18MC - 020	
Branch Name: RUNWAY 18/36			Use: RUNWAY
LCD: 6/4/2005 Surface Type: AAC Rank: P Section Area (sf): 497,500.00 Length (ft): 4,975.00 Width (ft): 100.00 From: SEE MAP To: SEE MAP		PCI Family: lowaAACRW_NE&N0	CE
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):		Section Comments:	
Last Insp Date: 3/12/2025 PCI: 60 Total Samples: 100 Surveyed: 10		Inspection Comments:	
Sample Number: 001			
Sample Type: R Sample PCI: 60 Sample Area (SF): 5,000	.00	Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	40.00 FT 263.00 FT 5,000.00 SF 5,000.00 SF	lu fs w
Sample Number: 011		-,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000	.00	Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	48.00 FT 233.00 FT 5,000.00 SF 5,000.00 SF	lu fs
Sample Number: 021			
Sample Type: R Sample PCI: 59 Sample Area (SF): 5,000	.00	Sample Comments:	
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L L M L L	90.00 FT 95.00 FT 165.00 FT 5,000.00 SF 5,000.00 SF	lu lu fs w
Sample Number: 031			
Sample Type: R Sample PCI: 58 Sample Area (SF): 5,000	.00	Sample Comments:	
48 L & T CR	L	10.00 FT	lu

Μ

6.00 FT

340.00 FT

5,000.00 SF

5,000.00 SF

ls

fs w

48 L & T CR

48 L & T CR

52 RAVELING

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW

Network ID: MCW					Page 24
Sample Number: 041					
Sample Type: R Sample PCI: 59	5 000 00	Sample	e Comments:		
Sample Area (SF):	5,000.00				
48 L & T CR		M	350.00 FT	fs w 2ndy	
52 RAVELING	NO	L	5,000.00 SF		
57 WEATHERI Sample Number: 053	NG	L	5,000.00 SF		
Sample Type: R		Sample	e Comments:		
Sample PCI: 64		Sample	e Comments.		
Sample Area (SF):	5,000.00				
48 L & T CR	0,000.00	1	42.00 FT	l	
52 RAVELING		L	43.00 FT 5,000.00 SF	lu	
57 WEATHERI	NC	L L	5,000.00 SF		
Sample Number: 063	NO	L	3,000.00 31		
Sample Type: R		Sample	e Comments:		
Sample PCI: 59		Cumpi	o Commonto.		
Sample Area (SF):	5,000.00				
48 L & T CR	•	L	6.00 FT	ls	
48 L & T CR		<u> </u>	82.00 FT	lu	
48 L & T CR		M	150.00 FT	fs	
52 RAVELING		L.	5,000.00 SF	10	
57 WEATHER	NG	Ĺ	5,000.00 SF		
Sample Number: 073			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Sample Type: R		Sample	e Comments:		
Sample PCI: 61		·			
Sample Area (SF):	5,000.00				
48 L & T CR		L	47.00 FT	lu	
48 L & T CR		М	230.00 FT	fs w	
52 RAVELING		L	5,000.00 SF		
57 WEATHERI	NG	L	5,000.00 SF		
Sample Number: 083					
Sample Type: R		Sample	e Comments:		
Sample PCI: 59					
Sample Area (SF):	5,000.00				
48 L & T CR	•	L	72.00 FT	lu	
48 L & T CR		M	250.00 FT	fs w	
52 RAVELING		L L	5,000.00 SF	15 W	
57 WEATHERI	NG	L	5,000.00 SF		
Sample Number: 093		<b>L</b>	0,000.00 01		
Sample Type: R		Sample	e Comments:		
Sample PCI: 59		Campi	S Commonto.		
Sample Area (SF):	5,000.00				
	5,500.00	1	5 00 FT	lu	
48 L & T CR 48 L & T CR		L M	5.00 FT 327.00 FT	lu fo w	
52 RAVELING			5,000.00 SF	fs w	
52 RAVELING	NO	L	5,000.00 5F		

5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW

Network ID: MCW			Page 25
	Branch - Section	on ID: R18MC - 030	
Branch Name: RUNWAY 18/36			Use: RUNWAY
LCD: 6/2/2005 Surface Type: AAC Rank: P Section Area (sf): 26,450.00 Length (ft): 529.00 Width (ft): 50.00 From: SEE MAP To: SEE MAP		PCI Family: IowaAACRW_NE&N	CE
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):		Section Comments:	
Last Insp Date: 3/12/2025 PCI: 62 Total Samples: 5 Surveyed: 4		Inspection Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,000.00		Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	30.00 FT 172.00 FT 5,000.00 SF 5,000.00 SF	lu fs w
Sample Number: 03			
Sample Type: R Sample PCI: 62 Sample Area (SF): 5,000.00		Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	27.00 FT 220.00 FT 5,000.00 SF 5,000.00 SF	lu fs w
Sample Number: 04			
Sample Type: R Sample PCI: 60 Sample Area (SF): 5,000.00		Sample Comments:	
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L L M L L	25.00 FT 20.00 FT 260.00 FT 5,000.00 SF 5,000.00 SF	ls lu fs w
Sample Number: 05			
Sample Type: R Sample PCI: 62		Sample Comments:	

6,450.00 Sample Area (SF):

> 48 L & T CR 313.00 FT fs w M 52 RAVELING 6,450.00 SF 57 WEATHERING 6,450.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW				Page 26
	Branch - Section ID:	R18MC - 040		
Branch Name: RUNWAY 18/36				Use: RUNWAY
LCD: 6/2/2005 Surface Type: AAC Rank: P Section Area (sf): 52,887.00 Length (ft): 529.00 Width (ft): 100.00 From: SEE MAP To: SEE MAP	PCI Fai	mily: lowaAACRW_NE&NC	CE	
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	Comments:		
Last Insp Date: 3/12/2025 PCI: 61 Total Samples: 10 Surveyed: 5	Inspect	ion Comments:		
Sample Number: 02				
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000.00  48 L & T CR 48 L & T CR	L M	28.00 FT 250.00 FT	lu fs w	
52 RAVELING 57 WEATHERING	L L	5,000.00 SF 5,000.00 SF		
Sample Number: 03				
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	22.00 FT 250.00 FT 5,000.00 SF 5,000.00 SF	lu w fs	
Sample Number: 06				
Sample Type: R Sample PCI: 60 Sample Area (SF): 5,000.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	36.00 FT 280.00 FT 5,000.00 SF 5,000.00 SF	lu fs w	
Sample Number: 08				
Sample Type: R Sample PCI: 59 Sample Area (SF): 5,000.00		Comments:		
48 L & T CR	H	7.00 FT	3in	

L

L

27.00 FT

143.00 FT

5,000.00 SF

5,000.00 SF

lu

fs w

48 L & T CR

48 L & T CR

52 RAVELING

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 27

Sample Number: 10

Sample Type: R Sample Comments:

Sample PCI: 64

Sample Area (SF): 6,450.00

48 L & T CR M 240.00 FT fs w

52 RAVELING L 6,450.00 SF 57 WEATHERING L 6,450.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW		Page 28
	Branch - Section ID: R18MC - 050	
Branch Name: RUNWAY 18/36		Use: RUNWAY
LCD: 6/2/2005 Surface Type: AAC Rank: P Section Area (sf): 49,836.00 Length (ft): 997.00 Width (ft): 50.00 From: SEE MAP To: SEE MAP	PCI Family: lowaAACRW_NE&NCE	
Slabs:	Section Comments:	
Slab Length (ft): Slab Width (ft): Joint Length (ft):		
Last Insp Date: 3/12/2025 PCI: 62 Total Samples: 10 Surveyed: 5	Inspection Comments:	
Sample Number: 02		
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000.00	Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L 27.00 FT lu M 240.00 FT fs w L 5,000.00 SF L 5,000.00 SF	
Sample Number: 03	·	
Sample Type: R Sample PCI: 62 Sample Area (SF): 5,000.00	Sample Comments:	
48 L & T CR	L 26.00 FT lu	
48 L & T CR	M 230.00 FT fs w	
52 RAVELING 57 WEATHERING	L 5,000.00 SF L 5,000.00 SF	
Sample Number: 05		
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,000.00	Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L 20.00 FT lu M 168.00 FT fs w L 5,000.00 SF L 5,000.00 SF	
Sample Number: 07	·	
Sample Type: R Sample PCI: 60 Sample Area (SF): 5,000.00	Sample Comments:	
40 L 0 T 0D	00.00 ET 1	

M

L

60.00 FT

250.00 FT

5,000.00 SF

5,000.00 SF

lu

w fs

48 L & T CR

48 L & T CR

52 RAVELING **57 WEATHERING** 

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 29

Sample Number: 09

Sample Type: R Sample Comments:

Sample PCI: 62

Sample Area (SF): 5,000.00

 48 L & T CR
 L
 17.00 FT
 lu

 48 L & T CR
 M
 225.00 FT
 fs w

 52 RAVELING
 L
 5,000.00 SF

52 RAVELING L 5,000.00 SF 57 WEATHERING L 5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW				Page 30
	Branch - Section ID:	R18MC - 060		
Branch Name: RUNWAY 18/36				Use: RUNWAY
LCD: 6/2/2005 Surface Type: AAC Rank: P Section Area (sf): 99,687.00 Length (ft): 997.00 Width (ft): 100.00 From: SEE MAP To: SEE MAP	PCI Fa	mily: lowaAACRW_NE&N0	CE	
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	n Comments:		
Last Insp Date: 3/12/2025 PCI: 60 Total Samples: 20 Surveyed: 5	Inspect	tion Comments:		
Sample Number: 02				
Sample Type: R Sample PCI: 62 Sample Area (SF): 5,000.00 48 L & T CR	Sample M	e Comments: 250.00 FT	fs w	
52 RAVELING 57 WEATHERING	L L	5,000.00 SF 5,000.00 SF	15 W	
Sample Number: 06				
Sample Type: R Sample PCI: 52 Sample Area (SF): 5,000.00	Sample	e Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	H L M L L	11.00 FT 60.00 FT 199.00 FT 5,000.00 SF 5,000.00 SF	3 in; 1 ft lu fs	
Sample Number: 09				
Sample Type: R Sample PCI: 61 Sample Area (SF): 5,000.00	Sample	e Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	20.00 FT 265.00 FT 5,000.00 SF 5,000.00 SF	lu fs w	
Sample Number: 14				
Sample Type: R Sample PCI: 64	Sample	e Comments:		

Sample Area (SF): 5,000.00

> 48 L & T CR 23.00 FT lu 48 L & T CR M 185.00 FT fs w 5,000.00 SF 52 RAVELING **57 WEATHERING** L 5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 31

Sample Number: 18

Sample Type: R Sample Comments:

Sample PCI: 63

Sample Area (SF): 5,000.00

48 L & T CR L 57.00 FT lu
48 L & T CR M 180.00 FT fs w

 52 RAVELING
 L
 5,000.00 SF

 57 WEATHERING
 L
 5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 32

Network ID: MCW			Page 32
Branch Name: TAXIWAY A	Branch - Sec	tion ID: TAMC - 010	Use: TAXIWAY
LCD: 6/2/2006 Surface Type: AAC Rank: P Section Area (sf): 287,735.0 Length (ft): 3,835.00 Width (ft): 75.00 From: SEE MAP To: SEE MAP	00	PCI Family: lowaAACTW_NE	
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):		Section Comments:	
Last Insp Date: 3/12/2025 PCI: 55 Total Samples: 51 Surveyed: 7		Inspection Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 51 Sample Area (SF): 5,	,625.00	Sample Comments:	
48 L & T CR 48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING	L M M L L	85.00 FT 400.00 FT 1.00 SF 5,624.00 SF 5,624.00 SF	lu fs w
Sample Number: 08			
Sample Type: R Sample PCI: 55 Sample Area (SF): 5,	,625.00	Sample Comments:	
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L L M L L	16.00 FT 80.00 FT 425.00 FT 5,625.00 SF 5,625.00 SF	ls lu fs
Sample Number: 10			
• • • • •	,200.00	Sample Comments:	
48 L & T CR 48 L & T CR 48 L & T CR 50 PATCHING 52 RAVELING 52 RAVELING 57 WEATHERING	L L M L H L	99.00 FT 69.00 FT 400.00 FT 14.00 SF 1.00 SF 4,905.00 SF 4,905.00 SF	lu Is fs w
57 WEATHERING		280.00 SF	PR

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 33

Network ID: MCW					Page 33
Sample Number: 20					
Sample Type: R Sample PCI: 59 Sample Area (SF):	5,625.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERI	ING	L M L L	68.00 FT 296.00 FT 5,625.00 SF 5,625.00 SF	lu fs w	
Sample Number: 30					
Sample Type: R Sample PCI: 55 Sample Area (SF):	5,625.00	Sample	e Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERI		L L M L L	39.00 FT 36.00 FT 442.00 FT 5,625.00 SF 5,625.00 SF	ls lu fs w	
Sample Number: 40			-,		
Sample Type: R Sample PCI: 59 Sample Area (SF):	5,625.00	Sample	e Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERI		L L M L L	19.00 FT 25.00 FT 338.00 FT 5,625.00 SF 5,625.00 SF	ls Iu fs w	
Sample Number: 48					
Sample Type: R Sample PCI: 61 Sample Area (SF):	5,625.00	Sample	e Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 48 L & T CR 57 WEATHER!	ING	H L L M L	4.00 FT 36.00 FT 44.00 FT 356.00 FT 5,625.00 SF	3in Iu Is fs w	

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 34

Network ID: MCVV				Page 34
Branch Name: TAXIWAY A	Branch - Section ID	: TAMC - 020		Use: TAXIWAY
LCD: 6/2/2005 Surface Type: AAC Rank: P Section Area (sf): 16,030.00 Length (ft): 185.00 Width (ft): 75.00 From: SEE MAP To: SEE MAP	PCI Fan	nily: lowaAACTW_NE		USE. TANIWAT
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	Comments:		
Last Insp Date: 3/12/2025 PCI: 58 Total Samples: 3 Surveyed: 3	Inspection	on Comments:		
Sample Number: 01				
Sample Type: R Sample PCI: 60 Sample Area (SF): 4,204.00	Sample	Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M M L L	8.00 FT 153.00 FT 108.00 FT 4,204.00 SF 4,204.00 SF	Is at break at break fs 2ndy fs 2ndy	
Sample Number: 02				
Sample Type: R Sample PCI: 57 Sample Area (SF): 6,196.00	Sample	Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L L M L L	30.00 FT 50.00 FT 422.00 FT 6,196.00 SF 6,196.00 SF	lu Is fs 2ndy	
Sample Number: 03				
Sample Type: R Sample PCI: 57 Sample Area (SF): 5,630.00	Sample	Comments:		
48 L & T CR	L	44.00 FT	lu	

M

L

390.00 FT

5,630.00 SF

5,630.00 SF

fs w

48 L & T CR

52 RAVELING

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 35

Branch - Section ID: TAMC - 030

Branch Name: TAXIWAY A

LCD: 4/5/2021
PCI Family: IowaACTW\_NE

Surface Type: AC
Rank: P
Section Area (sf): 98,795.00

Section Area (sf): 98,795.00 Length (ft): 1,975.00 Width (ft): 50.00 From: A01MC-35 To: EDGE

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

Last Insp Date: 3/12/2025 Inspection Comments:

PCI: 91 Total Samples: 20 Surveyed: 5

Sample Number: 04
Sample Type: R Sample Comments:

Sample PCI: 85

Sample Area (SF): 6,340.00

 48 L & T CR
 L
 14.00 FT
 lu

 48 L & T CR
 M
 35.00 FT
 w

 57 WEATHERING
 L
 6,340.00 SF

Sample Number: 08

Sample Type: R Sample Comments:

Sample PCI: 94

Sample Area (SF): 5,000.00

57 WEATHERING L 5,000.00 SF

Sample Number: 12

Sample Type: R Sample Comments:

Sample PCI: 94

Sample Area (SF): 5,000.00

57 WEATHERING L 5,000.00 SF

Sample Number: 16

Sample Type: R Sample Comments:

Sample PCI: 94

Sample Area (SF): 5,000.00

57 WEATHERING L 5,000.00 SF

Sample Number: 18

Sample Type: R Sample Comments:

Sample PCI: 90

Sample Area (SF): 5,500.00

48 L & T CR L 19.00 FT lu 57 WEATHERING L 5,500.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 36

	Branch - Section ID	: TBMC - 010		
Branch Name: TAXIWAY B				Use: TAXIWAY
LCD: 6/2/2006 Surface Type: AAC Rank: P Section Area (sf): 32,450.00 Length (ft): 435.00 Width (ft): 75.00 From: TA To: RW12	PCI Fa	mily: lowaAACTW_NE		
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	Comments:		
Last Insp Date: 3/12/2025 PCI: 60 Total Samples: 7 Surveyed: 4	Inspect	ion Comments:		
Sample Number: 02				
Sample Type: R Sample PCI: 54 Sample Area (SF): 3,985.00	Sample	Comments:		
48 L & T CR 52 RAVELING 57 WEATHERING 57 WEATHERING	M L H L	231.00 FT 3,729.00 SF 128.00 SF 3,729.00 SF	fs PR	
57 WEATHERING	M	128.00 SF	PR	
Sample Number: 03  Sample Type: R  Sample PCI: 59  Sample Area (SF): 5,625.00	Sample	• Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING 57 WEATHERING	L M L L	41.00 FT 30.00 FT 240.00 FT 5,400.00 SF 5,400.00 SF 225.00 SF	lu Is fs PR	
Sample Number: 04				
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,625.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING	L M L	23.00 FT 180.00 FT 5,625.00 SF	lu fs	

L

**57 WEATHERING** 

5,625.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 37

Sample Number: 05

Sample Type: R Sample Comments:

Sample PCI: 62

Sample Area (SF): 5,860.00

 48 L & T CR
 L
 29.00 FT
 Iu

 48 L & T CR
 M
 275.00 FT
 fs

 52 RAVELING
 L
 5,860.00 SF

 57 WEATHERING
 L
 5,860.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 38

Branch - Section ID: TBMC - 015

PCI Family: IowaAPCTW Northern

Branch Name: TAXIWAY B Use: TAXIWAY

LCD: 6/1/2006

Surface Type: APC

Rank: P

Section Area (sf): 11,522.00

Length (ft): 234.00 Width (ft): 50.00 From: RW12 To: TBMC-20

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

Last Insp Date: 3/12/2025 Inspection Comments:

PCI: 60 Total Samples: 2 Surveyed: 2

Sample Number: 01

Sample Type: R Sample Comments:

Sample PCI: 60

Sample Area (SF): 6,150.00

 48 L & T CR
 L
 45.00 FT
 lu

 48 L & T CR
 M
 323.00 FT
 fs

 52 RAVELING
 L
 6,150.00 SF

 57 WEATHERING
 L
 6.150.00 SF

Sample Number: 02

Sample Type: R Sample Comments:

Sample PCI: 60

Sample Area (SF): 5,372.00

 48 L & T CR
 L
 31.00 FT
 lu

 48 L & T CR
 M
 258.00 FT
 fs

 48 L & T CR
 M
 55.00 FT
 fs at break

52 RAVELING L 5,372.00 SF 57 WEATHERING L 5,372.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW			Page 39
	Branch - Sec	tion ID: TBMC - 020	
Branch Name: TAXIWAY B			Use: TAXIWAY
LCD: 6/3/2008 Surface Type: APC Rank: P Section Area (sf): 97,151.00 Length (ft): 1,933.00 Width (ft): 50.00 From: TBMC-15 To: TBMC-25		PCI Family: lowaAPCTW_Northern	
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):		Section Comments:	
Last Insp Date: 3/12/2025 PCI: 62 Total Samples: 19 Surveyed: 5		Inspection Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 62 Sample Area (SF): 5,000.00		Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	70.00 FT 185.00 FT 5,000.00 SF 5,000.00 SF	lu fs w
Sample Number: 05			
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,000.00		Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	26.00 FT 175.00 FT 5,000.00 SF 5,000.00 SF	lu fs w
Sample Number: 07			
Sample Type: R Sample PCI: 59 Sample Area (SF): 5,000.00		Sample Comments:	
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	7.00 FT 322.00 FT 5,000.00 SF 5,000.00 SF	lu fs w
Sample Number: 10			
Sample Type: R Sample PCI: 63 Sample Area (SF): 5,000.00		Sample Comments:	

M

L

51.00 FT

175.00 FT

5,000.00 SF

5,000.00 SF

lu

fs

48 L & T CR

48 L & T CR

52 RAVELING

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 40

Sample Number: 15

Sample Type: R Sample Comments:

Sample PCI: 63

Sample Area (SF): 5,000.00

 48 L & T CR
 L
 11.00 FT
 lu

 48 L & T CR
 M
 213.00 FT
 f w

 52 RAVELING
 L
 5,000.00 SF

 57 WEATHERING
 L
 5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 41

Network ID: MCW				Page 41
	Branch - Section ID	): TBMC - 025		
Branch Name: TAXIWAY B				Use: TAXIWAY
LCD: 6/2/2005 Surface Type: APC Rank: P Section Area (sf): 19,896.00 Length (ft): 228.00 Width (ft): 75.00 From: TBMC-20 To: RW18	PCI Fa	mily: lowaAPCTW_Northe	rn	
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	n Comments:		
Last Insp Date: 3/12/2025 PCI: 55 Total Samples: 4 Surveyed: 3	Inspect	tion Comments:		
Sample Number: 01				
Sample Type: R Sample PCI: 58 Sample Area (SF): 5,625.00	Sample	e Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L L M L L	31.00 FT 48.00 FT 320.00 FT 5,625.00 SF 5,625.00 SF	ls lu fs w	
Sample Number: 02				
Sample Type: R Sample PCI: 52 Sample Area (SF): 5,671.00	Sample	e Comments:		
48 L & T CR 48 L & T CR 48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	H L L M L	19.00 FT 10.00 FT 30.00 FT 300.00 FT 5,671.00 SF 5,671.00 SF	3in; 1 ft Is Iu fs w	
Sample Number: 03				
Sample Type: R Sample PCI: 55 Sample Area (SF): 5,263.00	Sample	e Comments:		
48 L & T CR 48 L & T CR	L M	101.00 FT 60.00 FT	lu at break fs	

323.00 FT

5,263.00 SF

5,263.00 SF

fs w

48 L & T CR

52 RAVELING

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW				Page 42
	Branch - Section ID	): TBMC - 030		
Branch Name: TAXIWAY B			Use	: TAXIWAY
LCD: 6/3/2008 Surface Type: AAC Rank: P Section Area (sf): 47,702.00 Length (ft): 1,933.00 Width (ft): 25.00 From: TBMC-35 To: TBMC-25	PCI Fa	mily: lowaAACTW_NE		
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	n Comments:		
Last Insp Date: 3/12/2025 PCI: 63 Total Samples: 10 Surveyed: 5	Inspec	tion Comments:		
Sample Number: 02				
Sample Type: R Sample PCI: 63 Sample Area (SF): 5,000.00	Sample	e Comments:		
48 L & T CR	L	26.00 FT	ls	
48 L & T CR	L	38.00 FT	lu	
48 L & T CR	M	152.00 FT	fs w	
52 RAVELING 57 WEATHERING	L L	5,000.00 SF 5,000.00 SF		
Sample Number: 03		0,000.00 01		
Sample Type: R	Sample	e Comments:		
Sample PCI: 59 Sample Area (SF): 5,000.00				
48 L & T CR	L	19.00 FT	lu	
48 L & T CR	Ĺ	100.00 FT	ls	
48 L & T CR	M	58.00 FT	fs	
52 RAVELING	L	5,000.00 SF		
57 WEATHERING	L	5,000.00 SF		
Sample Number: 04				
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,000.00	Sample	e Comments:		
48 L & T CR	L	23.00 FT	lu	
48 L & T CR	M	100.00 FT	fs w	
52 RAVELING	L	5,000.00 SF		
57 WEATHERING	L	5,000.00 SF		
Sample Number: 06	0	Commente		
Sample Type: R Sample PCI: 64	Sample	e Comments:		
Sample PCI. 04 Sample Area (SF): 5,000.00				
48 L & T CR	L	13.00 FT	lu	
48 L & T CR	M	82.00 FT	fs	
EO DAVELINO		E 000 00 CE		

52 RAVELING **57 WEATHERING**  5,000.00 SF

5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 43

Sample Number: 08

Sample Type: R Sample Comments:

Sample PCI: 64

Sample Area (SF): 5,000.00

 48 L & T CR
 L
 4.00 FT
 lu

 48 L & T CR
 M
 78.00 FT
 fs w

 52 RAVELING
 L
 5,000.00 SF

 57 WEATHERING
 L
 5,000.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 44

	4	TDIIO	~~=
Branch - S	COCTION II)	IRMC: -	. 1135
Dianti - u	CCUVII ID.		

Branch Name: TAXIWAY B Use: TAXIWAY

LCD: 6/1/2006 PCI Family: lowaAACTW\_NE

Surface Type: AAC

Rank: P

Section Area (sf): 8,092.00 Length (ft): 234.00 Width (ft): 25.00 From: RW12

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

To: TBMC-30

Last Insp Date: 3/12/2025 Inspection Comments:

PCI: 61 Total Samples: 2 Surveyed: 2

Sample Number: 01

Sample Type: R Sample Comments:

Sample PCI: 64

Sample Area (SF): 3,763.00

48 L & T CR 2.00 FT L lu 73.00 FT 48 L & T CR Μ fs w 48 L & T CR Μ 50.00 FT fs 52 RAVELING L 3.763.00 SF 57 WEATHERING L 3,763.00 SF

Sample Number: 02

Sample Type: R Sample Comments:

Sample PCI: 59

Sample Area (SF): 4,329.00

57 WEATHERING

48 L & T CR L 42.00 FT lu 48 L & T CR 45.00 FT M fs w 48 L & T CR 73.00 FT fs at break Μ 52 RAVELING L 4,304.00 SF 25.00 SF 52 RAVELING Μ

L

4,304.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW			Page	45
	Branch - Section ID	: TCMC - 010		
Branch Name: TAXIWAY C			Use: TAXIW	ΑY
LCD: 6/3/2008 Surface Type: AAC Rank: P Section Area (sf): 271,802.00 Length (ft): 3,625.00 Width (ft): 75.00 From: TB To: RW18	PCI Fan	nily: IowaAACTW_NE		
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	Comments:		
Last Insp Date: 3/12/2025 PCI: 62 Total Samples: 49 Surveyed: 7	Inspecti	on Comments:		
Sample Number: 04				
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,625.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	67.00 FT 70.00 FT 5,625.00 SF 5,625.00 SF	lu fs	
Sample Number: 09				
Sample Type: R Sample PCI: 62 Sample Area (SF): 5,625.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	11.00 FT 263.00 FT 5,625.00 SF 5,625.00 SF	lu fs	
Sample Number: 14				
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,625.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	L M L L	51.00 FT 80.00 FT 5,625.00 SF 5,625.00 SF	lu fs w	
Sample Number: 24				
Sample Type: R Sample PCI: 59 Sample Area (SF): 5,625.00	Sample	Comments:		
48 L & T CR 48 L & T CR 48 L & T CR	H L M	2.00 FT 17.00 FT 131.00 FT	3in Iu fs w	

L

5,625.00 SF

5,625.00 SF

52 RAVELING

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 46

Sample	Number:	34
--------	---------	----

Sample Type: R Sample Comments:

Sample PCI: 59

Sample Area (SF): 5,625.00

6.00 FT 48 L & T CR Н 3in 48 L & T CR L 26.00 FT lu 165.00 FT 48 L & T CR Μ w fs L 5,625.00 SF 52 RAVELING 57 WEATHERING L 5,625.00 SF

Sample Number: 39

Sample Type: R Sample Comments:

Sample PCI: 64

Sample Area (SF): 5,625.00

 48 L & T CR
 L
 10.00 FT

 48 L & T CR
 M
 139.00 FT
 fs w

 52 RAVELING
 L
 5,625.00 SF

 57 WEATHERING
 L
 5,625.00 SF

Sample Number: 44

Sample Type: R Sample Comments:

Sample PCI: 64

Sample Area (SF): 5,638.00

48 L & T CR M 79.00 FT fs 52 RAVELING L 5,638.00 SF

57 WEATHERING L 5,638.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 47

Network ID: MCW				Page 47
	Branch - Section ID	: TCMC - 020		
Branch Name: TAXIWAY C				Use: TAXIWAY
LCD: 6/2/2005 Surface Type: AAC Rank: P Section Area (sf): 17,885.00 Length (ft): 230.00 Width (ft): 75.00 From: TCMC-10 To: RW18	PCI Fan	nily: lowaAACTW_NE		
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section	Comments:		
Last Insp Date: 3/12/2025 PCI: 62 Total Samples: 4 Surveyed: 3	Inspection	on Comments:		
Sample Number: 01				
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,445.00	Sample	Comments:		
48 L & T CR 48 L & T CR 52 RAVELING 57 WEATHERING	M M L L	75.00 FT 114.00 FT 5,445.00 SF 5,445.00 SF	fs at break fs w	
Sample Number: 02				
Sample Type: R Sample PCI: 64 Sample Area (SF): 5,533.00	Sample	Comments:		
48 L & T CR 52 RAVELING 57 WEATHERING	M L L	222.00 FT 5,533.00 SF 5,533.00 SF	fs w	
Sample Number: 03				
Sample Type: R	Sample	Comments:		

Sample Type: R Sample Comments:

Sample PCI: 57

Sample Area (SF): 4,098.00

> 48 L & T CR Н 11.00 FT 3in 48 L & T CR 231.00 FT fs w Μ 52 RAVELING L 4,098.00 SF **57 WEATHERING** 4,098.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 48

Branch - Section ID: TH01MC - 010

PCI Family: IowaAsphaltTH Northern

Branch Name: T-HANGAR 01 Use: T-HANGAR

LCD: 7/4/2024 Surface Type: AC

Rank: P

Section Area (sf): 31,494.00

Length (ft): 900.00 Width (ft): 35.00 From: SEE MAP To: SEE MAP

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

Last Insp Date: 3/12/2025 Inspection Comments:

PCI: 100 Total Samples: 5 Surveyed: 4

Sample Number: 01

Sample Type: R Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,444.00

**NO DISTRESS** 

Sample Number: 02

Sample Type: R Sample Comments:

Sample PCI: 100

Sample Area (SF): 6,922.00

NO DISTRESS

Sample Number: 03

Sample Type: R Sample Comments:

Sample PCI: 100

Sample Area (SF): 6,100.00

NO DISTRESS

Sample Number: 04

Sample Type: R Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,223.00

**NO DISTRESS** 

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 49

Branch - Section ID: TH01MC - 020

Branch Name: T-HANGAR 01 Use: T-HANGAR

LCD: 1/1/2000

Surface Type: AC

Rank: P

Section Area (sf): 4,315.00 Length (ft): 105.00

Width (ft): 40.00 From: SEE MAP To: SEE MAP

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

Last Insp Date: 3/12/2025

PCI: 54 Total Samples: 1 Surveyed: 1 Inspection Comments:

PCI Family: IowaAsphaltTH Northern

Sample Number: 01

Sample Type: R Sample Comments:

Sample PCI: 54

Sample Area (SF): 4,315.00

41 ALLIGATOR CR L 10.00 SF 20.00 SF 41 ALLIGATOR CR Μ Edge 48 L & T CR L 77.00 FT lu 48 L & T CR Μ 175.00 FT fs w 57 WEATHERING М 4,315.00 SF

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 50

Network ID: MCW			Page 50
	Branch - Section ID:	TH01MC - 030	
Branch Name: T-HANGAR 01			Use: T-HANGAR
LCD: 1/1/1972 Surface Type: PCC Rank: P Section Area (sf): 40,756.00 Length (ft): 815.00 Width (ft): 50.00 From: SEE MAP To: SEE MAP	PCI F	amily: lowaPCCTH_NCE&NE	
Slabs: 261 Slab Length (ft): 12.50 Slab Width (ft): 12.50 Joint Length (ft): 5,655.83	Section	on Comments:	
Last Insp Date: 3/13/2025 PCI: 31 Total Samples: 19 Surveyed: 5	Inspec	ction Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 29 Sample Area (Slabs): 20.00	Samp	le Comments:	
62 CORNER BREAK 63 LINEAR CR 65 JT SEAL DMG 67 LARGE PATCH 71 FAULTING 71 FAULTING 72 SHAT. SLAB 75 CORNER SPALL	M M H L M M	2.00 Slabs 2.00 Slabs 20.00 Slabs 1.00 Slabs 2.00 Slabs 3.00 Slabs 3.00 Slabs 2.00 Slabs	
Sample Number: 03			
Sample Type: R Sample PCI: 14 Sample Area (Slabs): 20.00	Samp	le Comments:	
62 CORNER BREAK 63 LINEAR CR 65 JT SEAL DMG 71 FAULTING 71 FAULTING 72 SHAT. SLAB 74 JOINT SPALL	M M H L M M	1.00 Slabs 4.00 Slabs 20.00 Slabs 3.00 Slabs 1.00 Slabs 8.00 Slabs 1.00 Slabs	
Sample Number: 06			
Sample Type: R Sample PCI: 83 Sample Area (Slabs): 20.00	Samp	le Comments:	

M

Н

1.00 Slabs 20.00 Slabs

62 CORNER BREAK

65 JT SEAL DMG

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 51

Sample Number: 15			
Sample Type: R Sample PCI: 8 Sample Area (Slabs): 16.00	Sample	Comments:	
62 CORNER BREAK	M	2.00 Slabs	
63 LINEAR CR	M	4.00 Slabs	
65 JT SEAL DMG	Н	16.00 Slabs	
68 POPOUTS	N	6.00 Slabs	
71 FAULTING	L	1.00 Slabs	
71 FAULTING	M	2.00 Slabs	
72 SHAT. SLAB	Н	4.00 Slabs	

L

3.00 Slabs

#### Sample Number: 18

Sample Type: R Sample Comments:

Sample PCI: 15

Sample Area (Slabs): 20.00

72 SHAT. SLAB

Н	1.00 Slabs
M	1.00 Slabs
L	5.00 Slabs
M	3.00 Slabs
Н	20.00 Slabs
N	12.00 Slabs
L	6.00 Slabs
Н	4.00 Slabs
M	3.00 Slabs
	M L M H N L

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 52

Branch - Section ID: TH01MC - 035

Branch Name: T-HANGAR 01 Use: T-HANGAR

PCI Family: IowaAsphaltTH Northern

Inspection Comments:

Sample Comments:

LCD: 9/3/2021 Surface Type: AC

Rank: P

Section Area (sf): 128,421.00

Length (ft): 2,495.00 Width (ft): 50.00 From: TH01MC-30

To: END

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

Last Insp Date: 3/12/2025

PCI: 99

Total Samples: 26 Surveyed: 6

Sample Number: 02

Sample Type: R Sample Comments:

Sample PCI: 96

Sample Area (SF): 5,250.00

48 L & T CR L 17.00 FT lu

Sample Number: 05

Sample Type: R

Sample PCI: 100

Sample Area (SF): 5,250.00

NO DISTRESS

Sample Number: 12

Sample Type: R Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,320.00

NO DISTRESS

Sample Number: 17

Sample Type: R Sample Comments:

Sample PCI: 100

Sample Area (SF): 4,315.00

NO DISTRESS

Sample Number: 21

Sample Type: R Sample Comments:

Sample PCI: 95

Sample Area (SF): 5,250.00

48 L & T CR L 51.00 FT lu

Sample Number: 25

Sample Type: R Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,250.00

NO DISTRESS

Pavement Database: IA 2024 Generate Date: 8/11/2025

Network ID: MCW Page 53

Branch - Section ID: TH01MC - 040

Branch Name: T-HANGAR 01 Use: T-HANGAR

LCD: 7/4/2024 Surface Type: AC

Rank: P

Section Area (sf): 21,501.00

Length (ft): 396.00 Width (ft): 50.00 From: SEE MAP To: SEE MAP

Slabs: Section Comments:

Slab Length (ft): Slab Width (ft): Joint Length (ft):

Last Insp Date: 3/13/2025 Inspection Comments:

PCI: 100 Total Samples: 4 Surveyed: 3

Sample Number: 02

Sample Type: R

Sample PCI: 100

Sample Area (SF): 4,945.00

**NO DISTRESS** 

Sample Number: 03

Sample Type: R

Sample PCI: 100

Sample Area (SF): 5,990.00

**NO DISTRESS** 

Sample Number: 04

Sample Type: R Sample PCI: 100

Sample Area (SF): 6,014.00

**NO DISTRESS** 

PCI Family: IowaAsphaltTH Northern

Sample Comments:

Sample Comments:

Sample Comments:

# APPENDIX D WORK HISTORY REPORT

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

#### **Network: MASON CITY MUNICIPAL AIRPORT**

Branch - Section ID: A01MC - 010

 LCD: 6/2/2008
 Length (ft):
 236.00

 Use: APRON
 Width (ft):
 300.00

 Rank: P
 True Area (sf):
 70,816.00

Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2008	CR-PC	Complete Reconstruction - PCC	\$0.00	12.00	True	P501
06-01-2008	SB-AG	Subbase - Aggregate	\$0.00	8.00	False	P154
06-01-1968	OL-PF	Overlay - PCC Fully Bonded	\$0.00	6.00	True	-
06-02-1958	NC-PC	New Construction - PCC	\$0.00	8.00	True	-
06-01-1958	BA-AG	Base Course - Aggregate	\$0.00	7.00	False	-

#### Branch - Section ID: A01MC - 020

 LCD: 6/3/1972
 Length (ft):
 160.00

 Use: APRON
 Width (ft):
 90.00

 Rank: P
 True Area (sf):
 14,332.00

Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2020	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	EST
06-01-1999	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	-
06-03-1972	NC-PC	New Construction - PCC	\$0.00	10.00	True	P501
06-02-1972	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	P154
06-01-1972	SG-CO	Subgrade - Compacted	\$0.00	6.00	False	P152

#### Branch - Section ID: A01MC - 030

 LCD: 6/1/2017
 Length (ft):
 608.00

 Use: APRON
 Width (ft):
 125.00

 Rank: P
 True Area (sf):
 76,000.00

Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2017	CR-PC	Complete Reconstruction - PCC	\$0.00	0.00	True	FIELD EST
06-02-1999	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	-
06-01-1999	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	-
06-01-1968	CR-PC	Complete Reconstruction - PCC	\$0.00	8.00	True	-
06-02-1958	NC-PC	New Construction - PCC	\$0.00	8.00	True	EXTENDED IN 1972; 6" P152, 6" 154, 6" P501
06-01-1958	BA-AG	Base Course - Aggregate	\$0.00	7.00	False	P208

#### Branch - Section ID: A01MC - 035

 LCD: 4/5/2021
 Length (ft):
 1,464.00

 Use: APRON
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 73,174.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-05-2021	NC-AC	New Construction - AC	\$0.00	5.00	True	5" P-401 HMA surface course
04-04-2021	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P-209 aggregate base course
04-03-2021	SB-AG	Subbase - Aggregate	\$0.00	20.00	False	20" P-154 aggregate subbase course
04-02-2021	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" subgrade, 95% compaction

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

Branch - Section ID: A01MC - 040

 LCD: 6/1/2018
 Length (ft):
 250.00

 Use: APRON
 Width (ft):
 152.00

 Rank: P
 True Area (sf):
 38,255.00

Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	0.00	True	FIELD EST
06-02-1999	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	-
06-01-1999	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	-
06-03-1972	NC-PC	New Construction - PCC	\$0.00	6.00	True	P501
06-02-1972	SB-AG	Subbase - Aggregate	\$0.00	6.00	False	P154
06-01-1972	SG-CO	Subgrade - Compacted	\$0.00	6.00	False	P152

Branch - Section ID: A01MC - 050

 LCD: 6/3/2006
 Length (ft):
 460.00

 Use: APRON
 Width (ft):
 25.00

 Rank: P
 True Area (sf):
 11,660.00

Surface: AC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-03-2006	CR-AC	Complete Reconstruction - AC	\$0.00	6.00	True	6" P-401 AC SURFACE
06-02-2006	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-208 CABC
06-01-2006	SB-AG	Subbase - Aggregate	\$0.00	24.00	False	24" P-154 SUBBASE
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	-
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	-
06-02-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	-
06-01-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	-

Branch - Section ID: A01MC - 060

 LCD: 6/2/2009
 Length (ft):
 110.00

 Use: APRON
 Width (ft):
 156.00

 Rank: P
 True Area (sf):
 14,360.00

 Surface: AC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2009	CR-AC	Complete Reconstruction - AC	\$0.00	6.00	True	6" ASPHALT MAT
06-01-2009	SB-AG	Subbase - Aggregate	\$0.00	8.00	False	8" ROCK BASE

#### Branch - Section ID: A01MC - 070

 LCD: 6/1/1999
 Length (ft):
 130.00

 Use: APRON
 Width (ft):
 30.00

 Rank: P
 True Area (sf):
 3,843.00

Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-1999	CR-PC	Complete Reconstruction - PCC	\$0.00	6.00	True	6" PCC
06-03-1960	NC-PC	New Construction - PCC	\$0.00	6.00	True	P501
06-02-1960	SB-AG	Subbase - Aggregate	\$0.00	6.00	False	P154
06-01-1960	SG-CO	Subgrade - Compacted	\$0.00	6.00	False	P152

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

Branch - Section ID: A01MC - 080

 LCD: 8/3/2024
 Length (ft):
 229.00

 Use: APRON
 Width (ft):
 100.00

 Rank: P
 True Area (sf):
 22,940.00

Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-03-2024	NC-PC	New Construction - PCC	\$7,984,008.00	11.50	True	11.5" P-501 PCC
08-02-2024	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P-219 RECYCLED CONCRETE AGGREGATE BASE COURSE
08-01-2024	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	EXISTING SUBGRADE

Branch - Section ID: A01MC - 090

 LCD: 8/3/2024
 Length (ft):
 676.00

 Use: APRON
 Width (ft):
 23.00

 Rank: P
 True Area (sf):
 15,553.00

Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-03-2024	NC-PC	New Construction - PCC	\$7,984,008.00	8.00	True	8" P.C. CONCRETE CLASS C4
08-02-2024	SB-ST	Subbase - Stabilized	\$0.00	6.00	False	6" MODIFIED SUBBASE
08-01-2024	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	EXISTING SUBGRADE
03-05-2021	NC-IN	New Construction - Initial	\$0.00	0.00	True	-

Branch - Section ID: R12MC - 010

 LCD: 5/3/2006
 Length (ft):
 4,938.00

 Use: RUNWAY
 Width (ft):
 50.00

 Rank: S
 True Area (sf):
 245,643.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2017	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	EST
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
05-03-2006	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P-401 AC OVERLAY; 2005 CORE 10.7" P401/ 8" P208
05-02-2006	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	CRACK SEAL
05-01-2006	MI-CO	Cold Milling	\$0.00	-3.00	False	3" MILL AND REMOVE
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1974	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" (MIN) P401 AC; MANY AREAS HAVE 4"
06-03-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401 AC
06-02-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-208

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

Branch - Section ID: R12MC - 020

 LCD: 5/3/2006
 Length (ft):
 4,938.00

 Use: RUNWAY
 Width (ft):
 100.00

 Rank: S
 True Area (sf):
 493,057.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
05-03-2006	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P-401 AC OVERLAY; 2005 CORE 10.7" P401/ 8" P208
05-02-2006	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	CRACK SEAL
05-01-2006	MI-CO	Cold Milling	\$0.00	-3.00	False	3" MILL AND REMOVE
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1974	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" (MIN) P401 AC; MANY AREAS HAVE 4"
06-03-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401 AC
06-02-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208 ABC

Branch - Section ID: R12MC - 030

 LCD: 6/3/2005
 Length (ft):
 380.00

 Use: RUNWAY
 Width (ft):
 50.00

 Rank: S
 True Area (sf):
 18,816.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2017	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	EST
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-03-2005	CR-AC	Complete Reconstruction - AC	\$0.00	6.00	True	6" P-401 AC SURFACE
06-02-2005	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-208 CABC
06-01-2005	SB-AG	Subbase - Aggregate	\$0.00	24.00	False	24" P-154 SUBBASE
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" (MIN) P401 AC; MANY AREAS HAVE 4"
06-03-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401 AC
06-02-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208 ABC
06-01-1944	SG-CO	Subgrade - Compacted	\$0.00	24.00	False	24" P152 COMPACTED SUBGRADE

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

Branch - Section ID: R12MC - 040

 LCD: 6/3/2005
 Length (ft):
 380.00

 Use: RUNWAY
 Width (ft):
 100.00

 Rank: S
 True Area (sf):
 43,342.00

Surface: AC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2017	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	EST
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-03-2005	CR-AC	Complete Reconstruction - AC	\$0.00	6.00	True	6" P-401 AC SURFACE
06-02-2005	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-208 CABC
06-01-2005	SB-AG	Subbase - Aggregate	\$0.00	24.00	False	24" P-154 SUBBASE
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" (MIN) P401 AC; MANY AREAS HAVE 4"
06-03-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401 AC
06-02-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208 ABC
06-01-1944	SG-CO	Subgrade - Compacted	\$0.00	24.00	False	24" P152 COMPACTED SUBGRADE

Branch - Section ID: R18MC - 010

 LCD: 6/4/2005
 Length (ft):
 4,975.00

 Use: RUNWAY
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 248,664.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY; 2005 CORE 14.1" P401/8" P208
06-04-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	NORTH RW 4347': 4-8" P-401 AC OV; SOUTH RW 628': 8" P-401 NEW
06-03-2005	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	SOUTH RW 628': 8" P-208 CABC
06-02-2005	SB-AG	Subbase - Aggregate	\$0.00	24.00	False	SOUTH RW 628': 24" P-154 SUBBASE
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	NORTH RW 4347': 4" MILL; SOUTH RW 628': FULL DEPTH REMOVAL
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" (MIN) P401 AC OVERLAY; MANY AREAS HAVE 4"
06-01-1962	ST-SC	Surface Treatment - Seal Coat	\$0.00	0.00	False	-
06-01-1962	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-03-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401 AC
06-02-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208 ABC
06-01-1944	SG-CO	Subgrade - Compacted	\$0.00	24.00	False	24" P152 COMPACTED SUBGRADE

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

Branch - Section ID: R18MC - 020

 LCD: 6/4/2005
 Length (ft):
 4,975.00

 Use: RUNWAY
 Width (ft):
 100.00

 Rank: P
 True Area (sf):
 497,500.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY; 2005 CORE 14.1" P401/8" P208
06-04-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	NORTH RW 4347': 4-8" P-401 AC OV; SOUTH RW 628': 8" P-401 NEW
06-03-2005	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	SOUTH RW 628': 8" P-208 CABC
06-02-2005	SB-AG	Subbase - Aggregate	\$0.00	24.00	False	SOUTH RW 628': 24" P-154 SUBBASE
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	NORTH RW 4347': 4" MILL; SOUTH RW 628': FULL DEPTH REMOVAL
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" (MIN) P401 AC; MANY AREAS HAVE 4"
06-01-1962	ST-SC	Surface Treatment - Seal Coat	\$0.00	0.00	False	-
06-01-1962	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-03-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401 AC
06-02-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208 ABC
06-01-1944	SG-CO	Subgrade - Compacted	\$0.00	24.00	False	24" P152 COMPACTED SUBGRADE

Branch - Section ID: R18MC - 030

 LCD: 6/2/2005
 Length (ft):
 529.00

 Use: RUNWAY
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 26,450.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	4-8" P-401 AC OVERLAY; 2005 CORE 14" P401/6" P209
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	4" MILLING
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC OVERLAY
06-03-1968	NC-AC	New Construction - AC	\$0.00	5.00	True	5" P401 AC
06-02-1968	BA-BI	Base Course - Bituminous	\$0.00	4.50	False	4.5" P201 AC BASE
06-01-1968	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P209 CABC

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

Branch - Section ID: R18MC - 040

 LCD: 6/2/2005
 Length (ft):
 529.00

 Use: RUNWAY
 Width (ft):
 100.00

 Rank: P
 True Area (sf):
 52,887.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	4-8" P-401 AC OVERLAY; 2005 CORE: 14" P401/6" P209
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	4" MILLING
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC OVERLAY
06-03-1968	NC-AC	New Construction - AC	\$0.00	5.00	True	5" P401 AC
06-02-1968	BA-BI	Base Course - Bituminous	\$0.00	4.50	False	4.5" P201 AC BASE
06-01-1968	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P209 CABC

Branch - Section ID: R18MC - 050

 LCD: 6/2/2005
 Length (ft):
 997.00

 Use: RUNWAY
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 49,836.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	4-8" P-401 AC OVERLAY; 2005 CORE: 14" P401/SUBGRADE
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	4" MILLING
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC OVERLAY
06-04-1968	NC-AC	New Construction - AC	\$0.00	4.00	True	4" P401 AC
06-03-1968	BA-BI	Base Course - Bituminous	\$0.00	6.00	False	6" P201 AC BASE
06-02-1968	SG-CO	Subgrade - Compacted	\$0.00	15.00	False	15" P152
06-01-1968	SG-CO	Subgrade - Compacted	\$0.00	5.00	False	5" P152

Branch - Section ID: R18MC - 060

 LCD: 6/2/2005
 Length (ft):
 997.00

 Use: RUNWAY
 Width (ft):
 100.00

 Rank: P
 True Area (sf):
 99,687.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	4-8" P-401 AC OVERLAY; 2005 CORE 14" P401/SUBGRADE
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	4" MILLING
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	0.75	True	0.75" P402 PFC OVERLAY
06-04-1968	NC-AC	New Construction - AC	\$0.00	4.00	True	4" P401 AC
06-03-1968	BA-BI	Base Course - Bituminous	\$0.00	6.00	False	6" P201 AC BASE
06-02-1968	SG-CO	Subgrade - Compacted	\$0.00	15.00	False	15" P152
06-01-1968	SG-CO	Subgrade - Compacted	\$0.00	5.00	False	5" P152

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

Branch - Section ID: TAMC - 010

 LCD: 6/2/2006
 Length (ft):
 3,835.00

 Use: TAXIWAY
 Width (ft):
 75.00

 Rank: P
 True Area (sf):
 287,735.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2006	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P-401 AC OVERLAY
06-01-2006	MI-CO	Cold Milling	\$0.00	-3.00	False	2-4" MILL AND REMOVE
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" (MIN) P401 OVERLAY; WIDENED 25': 5"154, 15"P154, 6"P201, 4"P401
06-02-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401 AC
06-01-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208 ABC

Branch - Section ID: TAMC - 020

 LCD: 6/2/2005
 Length (ft):
 185.00

 Use: TAXIWAY
 Width (ft):
 75.00

 Rank: P
 True Area (sf):
 16,030.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	4-8" P-401 AC OVERLAY
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	4" MILLING
06-01-2005	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	MILL/OVERLAY (CROSS SECTION UNKNOWN)
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	P401 OVERLAY
06-04-1968	NC-AC	New Construction - AC	\$0.00	4.00	True	4" (MIN) P401 OVERLAY
06-03-1968	BA-BI	Base Course - Bituminous	\$0.00	6.00	False	6" P201 AC BASE
06-02-1968	SB-AG	Subbase - Aggregate	\$0.00	20.00	False	20" P154
06-01-1968	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	FROST PROTECTION P154

#### Branch - Section ID: TAMC - 030

 LCD: 4/5/2021
 Length (ft):
 1,975.00

 Use: TAXIWAY
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 98,795.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-05-2021	NC-AC	New Construction - AC	\$0.00	5.00	True	5" P-401 HMA surface course
04-04-2021	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P-209 aggregate base course
04-03-2021	SB-AG	Subbase - Aggregate	\$0.00	20.00	False	20" P-154 aggregate subbase course
04-02-2021	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" subgrade, 95% compaction

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW

Branch - Section ID: TBMC - 010

 LCD: 6/2/2006
 Length (ft):
 435.00

 Use: TAXIWAY
 Width (ft):
 75.00

 Rank: P
 True Area (sf):
 32,450.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2017	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	EST
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2006	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P-401 AC OVERLAY
06-01-2006	MI-CO	Cold Milling	\$0.00	-3.00	False	2-4" MILL AND REMOVE
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401 OVERLAY
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P401 OVERLAY; WIDENED 25' IN 1968: 5"154, 15"P154, 6"P201, 4"P401
06-02-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401
06-01-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208

Branch - Section ID: TBMC - 015

 LCD: 6/1/2006
 Length (ft):
 234.00

 Use: TAXIWAY
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 11,522.00

Surface: APC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-01-2006	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	MILL EXISTING AND 4" P401 OVERLAY; WITH RW12MC
06-02-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401 OVERLAY
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P401 OVERLAY
06-01-1949	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" P501 ON SUBGRADE

Branch - Section ID: TBMC - 020

 LCD: 6/3/2008
 Length (ft):
 1,933.00

 Use: TAXIWAY
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 97,151.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-03-2008	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P-401 OVERLAY
06-02-2008	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	CRACK SEALING
06-01-2008	MI-CO	Cold Milling	\$0.00	-3.00	False	2-4" MILL AND REMOVE
06-02-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401 OVERLAY
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P401
06-01-1949	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" P501 ON SUBGRADE

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW Page 10

Branch - Section ID: TBMC - 025

 LCD: 6/2/2005
 Length (ft):
 228.00

 Use: TAXIWAY
 Width (ft):
 75.00

 Rank: P
 True Area (sf):
 19,896.00

Surface: APC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	4-8" P-401 AC OVERLAY
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	4" MILLING
06-01-2005	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	MILL EXISTING AND OVERLAY (THICKNESS UNKNOWN); WITH RW18MC
06-02-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401 OVERLAY
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	MIN 4" P401 OVERLAY; WIDENED 25': 5"P154, 15" P154, 6"P201, 4"P401
06-01-1949	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" P501 ON SUBGRADE

Branch - Section ID: TBMC - 030

 LCD: 6/3/2008
 Length (ft):
 1,933.00

 Use: TAXIWAY
 Width (ft):
 25.00

 Rank: P
 True Area (sf):
 47,702.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-03-2008	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P-401 AC OVERLAY
06-02-2008	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	CRACK SEALING
06-01-2008	MI-CO	Cold Milling	\$0.00	-3.00	False	2-4" MILL AND REMOVE
06-02-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401 OVERLAY
06-04-1968	NC-AC	New Construction - AC	\$0.00	4.00	True	4" P401
06-03-1968	BA-BI	Base Course - Bituminous	\$0.00	6.00	False	6" P201 AC BASE
06-02-1968	SB-AG	Subbase - Aggregate	\$0.00	15.00	False	15" P154
06-01-1968	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	5" P154 FROST PROTECTION

#### Branch - Section ID: TBMC - 035

 LCD: 6/1/2006
 Length (ft):
 234.00

 Use: TAXIWAY
 Width (ft):
 25.00

 Rank: P
 True Area (sf):
 8,092.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-01-2006	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	MILL EXISTING AND 4" P401 OVERLAY; WITH RW12MC
06-02-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401 OVERLAY
06-04-1968	NC-AC	New Construction - AC	\$0.00	4.00	True	4" P401
06-03-1968	BA-BI	Base Course - Bituminous	\$0.00	6.00	False	6" P201 BIT BASE
06-02-1968	SB-AG	Subbase - Aggregate	\$0.00	15.00	False	15" P154
06-01-1968	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	5" P154 FROST PROTECTION

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW Page 11

Branch - Section ID: TCMC - 010

 LCD: 6/3/2008
 Length (ft):
 3,625.00

 Use: TAXIWAY
 Width (ft):
 75.00

 Rank: P
 True Area (sf):
 271,802.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-03-2008	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P-401 AC OVERLAY
06-02-2008	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	CRACK SEALING
06-01-2008	MI-CO	Cold Milling	\$0.00	-3.00	False	2-4" MILL AND REMOVE
06-02-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401 OVERLAY
06-01-1968	OL-AS	Overlay - AC Structural	\$0.00	4.00	True	4" P401 OVERLAY
06-02-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401
06-01-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208

Branch - Section ID: TCMC - 020

 LCD: 6/2/2005
 Length (ft):
 230.00

 Use: TAXIWAY
 Width (ft):
 75.00

 Rank: P
 True Area (sf):
 17,885.00

Surface: AAC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	WIDE CRACKS ONLY
06-02-2005	OL-AS	Overlay - AC Structural	\$0.00	6.00	True	4-8" P-401 AC OVERLAY
06-01-2005	MI-CO	Cold Milling	\$0.00	-4.00	False	4" MILLING
06-01-2005	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	MILL EXISTING AND OVERLAY (THICKNESS UNKNOWN) WITH RW18MC-60
06-02-1993	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1993	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-1977	OL-AS	Overlay - AC Structural	\$0.00	1.50	True	1.5" P401 OVERLAY
06-04-1968	NC-AC	New Construction - AC	\$0.00	4.00	True	4" P401
06-03-1968	BA-BI	Base Course - Bituminous	\$0.00	6.00	False	6" P201 AC BASE
06-02-1968	SB-AG	Subbase - Aggregate	\$0.00	15.00	False	15" P154
06-01-1968	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	5" P154 FROST PROTECTION
06-02-1944	NC-AC	New Construction - AC	\$0.00	3.00	True	3" P401 AC SURFACE
06-01-1944	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P208 ABC

#### Branch - Section ID: TH01MC - 010

 LCD: 7/4/2024
 Length (ft):
 900.00

 Use: T-HANGAR
 Width (ft):
 35.00

 Rank: P
 True Area (sf):
 31,494.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
07-04-2024	CR-AC	Complete Reconstruction - AC	\$139,165.00	2.00	True	2" SURFACE COURSE HMA PAVEMENT, STANDARD TRAFFIC (ST), 1/2" PG 58-28H
07-03-2024	BA-BI	Base Course - Bituminous	\$0.00	3.00	False	3" BASE COURSE HMA PAVEMENT, STANDARD TRAFFIC (ST), 1/2" PG 58-28H
07-02-2024	SB-AG	Subbase - Aggregate	\$0.00	10.00	False	10" IOWA DOT MODIFIED SUBBASE
07-01-2024	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" SUBGRADE PREP
01-01-2000	NC-AC	New Construction - AC	\$0.00	0.00	True	EST. VIA GE

Pavement Database: IA 2024 Generate Date: 6/30/2025

Network ID: MCW Page 12

#### Branch - Section ID: TH01MC - 020

 LCD: 1/1/2000
 Length (ft):
 105.00

 Use: T-HANGAR
 Width (ft):
 40.00

 Rank: P
 True Area (sf):
 4,315.00

Surface: AC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-2000	NC-AC	New Construction - AC	\$0.00	0.00	True	EST. VIA GE

#### Branch - Section ID: TH01MC - 030

 LCD: 1/1/1972
 Length (ft):
 815.00

 Use: T-HANGAR
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 40,756.00

Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-1972	NC-PC	New Construction - PCC	\$0.00	0.00	True	DATE UNKNOWN; CONSTRUCTED PRIOR TO 1994

#### Branch - Section ID: TH01MC - 035

 LCD: 9/3/2021
 Length (ft):
 2,495.00

 Use: T-HANGAR
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 128,421.00

Surface: AC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
09-03-2021	NC-AC	New Construction - AC	\$0.00	5.00	True	5" P-401 HMA pavement
09-02-2021	BA-AG	Base Course - Aggregate	\$0.00	12.00	False	12" P-208 aggregate base course
09-01-2021	SG-CO	Subgrade - Compacted	\$0.00	6.00	False	6" P-152 subgrade. 95% compaction

#### Branch - Section ID: TH01MC - 040

 LCD: 7/4/2024
 Length (ft):
 396.00

 Use: T-HANGAR
 Width (ft):
 50.00

 Rank: P
 True Area (sf):
 21,501.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
07-04-2024	CR-AC	Complete Reconstruction - AC	\$294,270.00	2.00	True	2" SURFACE COURSE HMA PAVEMENT, STANDARD TRAFFIC (ST), 1/2", PG 58-28H
07-03-2024	BA-BI	Base Course - Bituminous	\$0.00	2.00	False	2" BASE COURSE HMA PAVEMENT, STANDARD TRAFFIC (ST), 1/2", PG 58-28H
07-02-2024	SB-AG	Subbase - Aggregate	\$0.00	8.00	False	8" IOWA DOT MODIFIED SUBBASE
07-01-2024	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" SUBGRADE
01-01-1972	NC-PC	New Construction - PCC	\$0.00	0.00	True	DATE UNKNOWN; CONSTRUCTED PRIOR TO 1994

### **APPENDIX E**

## LOCALIZED PREVENTIVE MAINTENANCE POLICIES AND UNIT COST TABLES

Table E-1. Localized preventive maintenance policy, asphalt-surfaced pavements.

Distress Type	Severity Level	Maintenance Action		
Alligator Cracking	Low	Monitor		
Alligator Cracking	Medium	Asphalt Patch		
Alligator Cracking	High	Asphalt Patch		
Bleeding	N/A	Monitor		
Block Cracking	Low	Monitor		
Block Cracking	Medium	Crack Seal—Asphalt		
Block Cracking	High	Crack Seal—Asphalt		
Corrugation	Low	Monitor		
Corrugation	Medium	Asphalt Patch		
Corrugation	High	Asphalt Patch		
Depression	Low	Monitor		
Depression	Medium	Monitor		
Depression	High	Asphalt Patch		
Jet-Blast Erosion	N/A	Asphalt Patch		
Joint Reflection Cracking	Low	Monitor		
Joint Reflection Cracking	Medium	Crack Seal—Asphalt		
Joint Reflection Cracking	High	Crack Seal—Asphalt		
L&T Cracking	Low	Monitor		
L&T Cracking	Medium	Crack Seal—Asphalt		
L&T Cracking	High	Crack Seal—Asphalt		
Oil Spillage	N/A	Asphalt Patch		
Patching	Low	Monitor		
Patching	Medium	Asphalt Patch		
Patching	High	Asphalt Patch		
Polished Aggregate	N/A	Monitor		
Raveling	Low	Monitor		
Raveling	Medium	Asphalt Patch		
Raveling	High	Asphalt Patch		
Rutting	Low	Monitor		
Rutting	Medium	Monitor		
Rutting	High	Asphalt Patch		
Shoving	Low	Monitor		
Shoving	Medium	Asphalt Patch		
Shoving	High	Asphalt Patch		
Slippage Cracking	N/A	Asphalt Patch		
Swelling	Low	Monitor		
Swelling	Medium	Monitor		
Swelling	High	Asphalt Patch		
Weathering	Low	Monitor		
Weathering	Medium	Monitor		
Weathering	High	Asphalt Patch		

Table E-2. Localized preventive maintenance policy, PCC pavements.

Carravita						
Distress Type	Severity Level	Maintenance Action				
ASR	Low	Monitor				
ASR	Medium	Slab Replacement				
ASR	High	Slab Replacement				
Blowup	Low	Slab Replacement				
Blowup	Medium	Slab Replacement				
Blowup	High	Slab Replacement				
Corner Break	Low	Crack Seal—PCC				
Corner Break	Medium	Full Depth PCC Patch				
Corner Break	High	Full Depth PCC Patch				
Durability Cracking	Low	Monitor				
Durability Cracking	Medium	Full Depth Patch				
Durability Cracking	High	Slab Replacement				
Faulting	Low	Monitor				
Faulting	Medium	Grinding				
Faulting	High	Slab Replacement				
Joint Seal Damage	Low	Monitor				
Joint Seal Damage	Medium	Joint Seal				
Joint Seal Damage	High	Joint Seal				
LTD Cracking	Low	Monitor				
LTD Cracking	Medium	Crack Seal—PCC				
LTD Cracking	High	Slab Replacement				
Patching (Small and Large)	Low	Monitor				
Patching (Small and Large)	Medium	Full Depth PCC Patch				
Patching (Small and Large)	High	Full Depth PCC Patch				
Popouts	N/A	Monitor				
Pumping	N/A	Monitor				
Scaling	Low	Monitor				
Scaling	Medium	Partial Depth PCC Patch				
Scaling	High	Slab Replacement				
Shattered Slab	Low	Crack Seal—PCC				
Shattered Slab	Medium	Slab Replacement				
Shattered Slab	High	Slab Replacement				
Shrinkage Cracking	N/A	Monitor				
Spalling (Joint and Corner)	Low	Monitor				
Spalling (Joint and Corner)	Medium	Partial Depth PCC Patch				
Spalling (Joint and Corner)	High	Partial Depth PCC Patch				

Table E-3. 2025 unit costs for localized preventive maintenance actions.

Maintenance Action	Unit Cost		
Asphalt Patch—Asphalt-Surfaced Pavement	\$15.90/sf		
Crack Sealing—Asphalt-Surfaced Pavement	\$2.72/If		
Partial Depth PCC Patch—PCC Pavement	\$40.74/sf		
Full Depth PCC Patch—PCC Pavement	\$18.19/sf		
Crack Sealing—PCC Pavement	\$3.27/lf		
Joint Sealing—PCC Pavement	\$3.27/lf		
Grinding—PCC Pavement	\$0.39/sf		
Slab Replacement—PCC Pavement	\$18.19/sf		

Table Note: The unit cost estimates are based on broad statewide numbers and should be adjusted to reflect local costs.

Table E-4. 2025 unit costs (per square foot) based on pavement type and PCI ranges.

Pavement Type	PCI Range 0-40	PCI Range 40-50	PCI Range 50-60	PCI Range 60-70	PCI Range 70-80	PCI Range 80-90	PCI Range 90-100
Asphalt- surfaced	\$11.29	\$5.34	\$5.34	\$5.34	\$0.00	\$0.00	\$0.00
PCC	\$18.86	\$8.92	\$8.92	\$8.92	\$0.00	\$0.00	\$0.00

#### Table Notes:

- The unit cost estimates are based on broad statewide numbers and should be adjusted to reflect local costs.
- Pavement Type: Asphalt-surfaced = AC (asphalt cement concrete), AAC (asphalt overlay on AC), or APC (asphalt overlay on PCC); PCC = portland cement concrete

### **APPENDIX F**

# YEAR 2025 LOCALIZED PREVENTIVE MAINTENANCE DETAILS

Year 2025 Localized Preventive Maintenance Details

Table F-1. Year 2025 localized preventive maintenance details.

Branch	Section	Distress Type	Severity	Distress Quantity	Distress Unit	Maintenance Action	Unit Cost	2025 Estimated Cost
A01MC	10	Joint Seal Damage	High	322	Slabs	Joint Seal (Localized)	\$3.27	\$29,477
A01MC	20	Corner Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$40.74	\$151
A01MC	20	Joint Seal Damage	High	33	Slabs	Joint Seal (Localized)	\$3.27	\$2,274
A01MC	20	Joint Spalling	Medium	3	Slabs	Patching - PCC Partial Depth	\$40.74	\$727
A01MC	20	LTD Cracking	Medium	1	Slabs	Crack Sealing - PCC	\$3.27	\$53
A01MC	20	Small Patch	Medium	1	Slabs	Patching - PCC Full Depth	\$18.19	\$68
A01MC	30	Corner Spalling	High	2	Slabs	Patching - PCC Partial Depth	\$40.74	\$251
A01MC	30	Joint Spalling	Medium	2	Slabs	Patching - PCC Partial Depth	\$40.74	\$603
A01MC	30	LTD Cracking	Medium	7	Slabs	Crack Sealing - PCC	\$3.27	\$353
A01MC	40	Joint Spalling	Medium	3	Slabs	Patching - PCC Partial Depth	\$40.74	\$813
A01MC	40	LTD Cracking	Medium	2	Slabs	Crack Sealing - PCC	\$3.27	\$76
TAMC	30	L&T Cracking	Medium	129	Ft	Crack Sealing - AC	\$2.72	\$350

#### Table Notes:

- 1. See Figure 3 for the location of the branch and section.
- 2. Distress types are defined by ASTM D5340. L&T cracking = longitudinal and transverse cracking; LTD cracking = longitudinal, transverse, and diagonal cracking; ASR = alkali-silica reaction.
- 3. The costs provided are of a general nature for the entire State and may require adjustments to reflect specific conditions at Mason City Municipal Airport.



#### PREPARED FOR

Iowa Department of Transportation Modal Transportation Bureau 800 Lincoln Way Ames, Iowa 50010 515-239-1691 https://iowadot.gov/modes-travel/aviation

AUGUST 2025