21A-49


## **Reference List**

Design Manual Chapter 21 Automation Tools Instructions

Originally Issued: 12-31-08


Revised: 04-30-09

This tool can be accessed from the  $\underline{\text{Geopak}}$ : D&C Manager, as shown below: (If the item is not found as shown below, use the D&C > Edit > Find tool to locate it.)



The **Reference List** command will produce a printable listing of all references and nested reference attachments to the active model.

When the Reference List command is double-clicked, the following dialog will display.



Clicking the List button will produce the following on-screen printable listing.

