

HMA Verification Responsibilities			
Duty	Task	Performed By / REQ'D. CERT.	Minimum Frequency
5. Verify Compacted Pavement Properties.	- Select random sample locations. - Direct and witness contractor coring. - Inspect cores for damage and thickness and direct replacement coring of damaged or unusable cores. - Take possession of cores and transport to the contractors lab or secure core samples if contractor is transporting the cores. - Measure cores for thickness. - Test cores for density and record weights. - Provide copy of thickness and weights to contractor for reporting.	Construction HMA SAMPLER	8 Cores/Lot (PWL) 7 Cores/Lot (non-PWL)
	- Select random sections for smoothness testing. - Perform independent smoothness testing. - Compare results to contractor test results per IM 216. - Report validation results. - Investigate validation issues.	District Materials PROFILOMETER	10% of Project
		District Materials	As Needed

