



# COGO Alignments, Plan View



Design Manual  
Chapter 21  
Automation Tools  
Instructions

Originally Issued: 09-20-10

This tool can be accessed from the Geopak: D&C Manager, as shown at the right.


(If the item is not found as shown, use the *D&C > Edit > Find* tool to locate it.)

After *double-clicking* the **COGO Alignments** item, the **COGO Alignments** dialog, for Horizontal Alignments, will display, as shown below.





*Double-clicking* either the “English...” or the “Metric Horizontal Alignment” tool, (shown above), will run a program that will determine the resolution and scale of the open model, to be used later to populate the **Geopak Label Scale** field on the **Draw Plan & Profile** dialog.

*Double-clicking* either of the two above listed tools will also activate the “Draw Plan and Profile” button on the **Horizontal Alignment** dialog, as shown by the arrow at the right.




Clicking the “Draw Plan & Profile” button will activate the “Open Job” dialog, shown at the right. Select the appropriate “gpk” file, (job), and click the **OK** button. This will produce the **Draw Plan & Profile** dialog, shown below.



The **Element Type** drop-down list, shown at the right, provides the options for:


- Lines,**
- Curves,**
- Spirals,**
- Chains,**
- Stationing**, and more.



The “**Lines**” **Element Type** provides the three options listed below and shown at the right.

- Line Direction Labels,**
- Line Length Labels, and**
- Line Labels Only**


Any or all of the options can be selected. A “**Line**” must also be selected from the “**Select Line to Draw**” list, if any are available.



If the “**Curves**” **Element Type** is selected, the options change as listed below, and as shown at the right.

- Curve Labels**
- Curve Data**
- Curve Labels Only**
- Place Curve Data by DP**


As mentioned above for **Lines**, a “**Curve**” must also be selected from the “**Select Curve to Draw**” list.




Selecting the “**Spirals**” **Element Type** produces the following option list:

- Spiral Labels**
- Spiral Data**
- Spiral Labels Only**
- Place Spiral Data by DP**

As mentioned above for the other **Element Types**, a **Spiral** name must also be selected from the list.



The “**Chains**” Element Type produces a longer list of options, as shown at the right.



The options available when the “**Stationing**” Element Type is selected, are shown below.

The *drop-down* lists under both the **Large** and **Small Ticks** items provide several additional options, as listed and shown below.

- Ticks Left; Labels Left**
- Ticks Right; Labels Right**
- Ticks Both; Labels Left**
- Ticks Both; Labels Right**

There are also additional options under the **Control Point Labels** item, as listed and shown below.

- As Per Preferences**
- Force Left**
- Force Right**

In all the examples above, the desired *check-box* options should be checked () before selecting the “**Line, Curve, Spiral, Chain, or Stationing item to Draw**” from the list. The process will begin immediately after an item is selected.

