

262_08
4/15/25

WEIGH IN MOTION SENSORS

Weigh In Motion (WIM) sensors are located within this project's construction limits NB (MP # & #)
Notify the Iowa DOT's Office of Systems Planning (telephone number 515-239-1664) a minimum of 7 days prior to working near the WIM installations. Transportation Data personnel will locate and mark the WIM's one time. Treat these WIM systems similar to other public utilities. The Contractor is responsible for paying for unapproved damage they have caused to the WIM systems.