

HMA Verification Responsibilities			
Duty	Task	Performed By / REQ'D. CERT.	Minimum Frequency
5. Verify Compacted Pavement Properties.	• Select random sample locations. • Direct and witness contractor coring. • Inspect cores for damage and thickness and direct replacement coring of damaged or unusable cores. • Take possession of cores and transport to the contractor's lab or secure core samples if contractor is transporting the cores. • Measure cores for thickness. • Test cores for density and record weights. • Provide copy of thickness and weights to contractor for reporting.	Construction HMA SAMPLER	8 Cores/Lot
	• Select random sections for smoothness testing. • Perform independent smoothness testing. • Compare results to contractor test results per IM 216. • Report validation results.		
	• Investigate validation issues.	District Materials PROFILOMETER	10% of Project
		District Materials	As Needed

