
******THIS IS A NEW APPENDIX. – PLEASE READ CAREFULLY.******

**Procedure to Determine Datum Temperature
Setting for Humboldt type Maturity Meters**

<u>Key</u>	<u>Displays</u>
Press ENTER	PRESENT VALUES CH 1 Temp: XX
Press REC	RECORDING 1. START
Press REC	SETUP 1. DATUM TEMP
Press ENTER	SETUP DATUM TEMP: -10 °C

If datum temperature is not set to -10° C, press the up (↑) or down (↓) arrows to set the maturity meter to -10 °C. Then press ENTER to save the settings.

Setting datum temperature varies for other maturity meters. Consult the manual from the manufacturer.